



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA EASY
Colour	Black
Year of manufacture	2015
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 3

Date	2021-12-18
Pictures	24
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 2

Date	2021-12-04
Pictures	3
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-12-03
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-01
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	21
Total items failed	14

MOT #12	2024-02-02 15:21
MOT test number	529155303160
Result	✓ Passed
Next expiry date	2025-02-01
Advice	Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2024-02-02 10:02

**MOT test number**

954537239342

**Result****✗ Failed**

**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

**Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MOT #10**

2022-12-21 09:21

**MOT test number**

830291738492

**Result****✓ Passed****MOT #9**

2022-12-20 14:38

**MOT test number**

633974818236

**Result****✗ Failed**

**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #8** 2021-12-10 14:51**MOT test number** 319150312021**Result** ✓ Passed**Advice** Front suspension arm bushes deteriorated**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #7** 2021-08-17 15:24**MOT test number** 735961201774**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #6** 2021-08-16 09:15**MOT test number** 177578812897**Result** ✗ Failed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Exhaust has a major leak of exhaust gases flexi joint (6.1.2 (a))**Fail** Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))**MOT #5** 2020-08-10 15:54**MOT test number** 475325526285**Result** ✓ Passed**MOT #4** 2020-08-10 08:39**MOT test number** 884095540560**Result** ✗ Failed**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

**MOT #3** 2019-08-01 13:05**MOT test number** 619466141709**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2019-08-01 08:19**MOT test number** 552721859138**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2018-08-18 09:35**MOT test number** 970295911519**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Small chip in windscreen



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 February 2025

✓  
**MOT**

**Expires:**  
1 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	1 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2015-09-30
Last registration	2024-02-02
Complete history	<a href="#">See info</a>



Registration #1	2015-09-30	27 mi
Registration #2	2018-08-18	55.537 mi
Registration #3	2019-08-01	75.251 mi
Registration #4	2019-08-01	75.251 mi
Registration #5	2020-08-10	85.606 mi
Registration #6	2020-08-10	85.606 mi
Registration #7	2021-08-16	92.205 mi
Registration #8	2021-08-17	92.208 mi
Registration #9	2022-08-01	100.000 mi
Registration #10	2022-08-01	100.000 mi
Registration #11	2023-08-01	100.000 mi
Registration #12	2023-08-01	100.000 mi
Registration #13	2023-08-01	100.000 mi
Registration #14	2023-08-01	100.000 mi
Registration #15	2023-08-01	100.000 mi
Registration #16	2024-02-02	100.000 mi

More info >



## Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

## Safety ratings

NCAP rating	★★★★☆
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	<a href="#">see crash video</a>



## Dimensions &amp; weight

Width	1643 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

## Additional information

Fuel tank capacity	37 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	1406327