



BTIOXYF

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 350 LWB HR P/V 115
Colour	White
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	310 Nm at 1.750 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel





MOT history

MOT expiry date	2021-09-21
MOT pass rate	53 %
MOT passed	8
Failed MOT tests	7
Total advice items	26
Total items failed	22

MOT #15	2020-09-22 15:37
MOT test number	864009258914
Result	✓ Passed
Next expiry date	2021-09-21

MOT #14	2020-09-17 09:28
MOT test number	119002164020
Result	✗ Failed

- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Outer Integral body structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired sill (6.2.2 (d) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Outer Integral body structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired sill (6.2.2 (d) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #13	2019-05-14 15:16
MOT test number	308404074453
Result	✓ Passed

- Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #12** 2019-05-13 15:34**MOT test number** 508117612302**Result** ✗ Failed

- Fail** Offside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #11 2018-05-17 15:54**MOT test number** 508981104734**Result** ✓ Passed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #10 2018-05-17 15:54**MOT test number** 303330984850**Result** ✗ Failed

- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #9 2017-05-18 16:02**MOT test number** 754732875457**Result** ✓ Passed

**MOT #8**

2017-05-16 15:33

MOT test number

132430290042

Result

✗ Failed

- Advice** Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Brake pipe excessively corroded front to rear (3.6.B.2c)
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #7

2016-05-09 13:35

MOT test number

691379595112

Result

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside front and offside front tyres worn on outer edges
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Front front brake fluctuating, but not excessively (3.7.B.3)



MOT #6

2016-05-09 13:35

MOT test number

628266833035

Result

✗ Failed

Pass with rectification

Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice

Nearside front and offside front tyres worn on outer edges

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice

Front front brake fluctuating, but not excessively (3.7.B.3)

MOT #5

2015-05-21 13:37

MOT test number

439031145107

Result

✓ Passed

Notice

Both rear diff seals seeping

Advice

Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice

Nearside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #4** 2015-05-20 15:28**MOT test number** 595890445199**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Notice** Both rear diff seals seeping**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #3** 2014-07-24 08:50**MOT test number** 407215504242**Result** ✓ Passed**MOT #2** 2014-07-23 15:42**MOT test number** 646654804218**Result** ✗ Failed**Fail** Fuel pipe leaking (7.2.3)**MOT #1** 2013-05-01 09:39**MOT test number** 298451723409**Result** ✓ Passed



Tax & MOT check

X
Untaxed

Tax expired:
15 June 2021

X
MOT

Expired:
21 September 2021

Tax status	Expired at 15 June 2021
Days left	1050 days too late
MOT expiry date	21 September 2021
Full MOT history	See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	BT10XYF
Plate since	2019-03-29
Current registration	BT10XYF
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-08-13
Last registration	2020-09-22
Complete history	See info



Registration #1	2010-08-13	16 mi
Registration #2	2013-05-01	59.583 mi
Registration #3	2014-07-23	76.144 mi
Registration #4	2014-07-24	76.144 mi
Registration #5	2015-05-20	96.997 mi
Registration #6	2015-05-21	96.997 mi
Registration #7	2016-05-09	114.586 mi
Registration #8	2016-05-09	114.586 mi
Registration #9	2016-05-09	114.586 mi
Registration #10	2016-05-09	114.586 mi
Registration #11	2016-05-09	114.586 mi
Registration #12	2016-05-09	114.586 mi
Registration #13	2016-05-09	114.586 mi
Registration #14	2016-05-09	114.586 mi
Registration #15	2016-05-09	114.586 mi
Registration #16	2016-05-09	114.586 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2360 mm
Height	2601 mm
Length	5680 mm
Kerb weight	1790 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	AT18351