





report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO POP
Colour	White
Year of manufacture	2013
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	126 g/km
CO2 label	D



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2022-01-26

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-07
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	17
Total items failed	11

MOT #13		2024-04-08 14:51
MOT test	number	728231999217
Result		✓ Passed
Next expi	ry date	2025-04-07
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2024-04-02 13:43
MOT test number	636484508806
Result	× Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's spe (a))	cified limits (8.2.1.2

CarCheck.co.uk page 3/13



MOT #11 2023-02-27 13:25
MOT test number 928184195209

Result ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2022-02-22 12:44

MOT test number 898977259305

Result ✓ Passed

MOT #9 2021-03-11 12:00

MOT test number 841858858616

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing perish inner and outer tread (5.2.3 (d) (ii))

Advice Clutch anti slip mising

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing perish inner and outer tread (5.2.3 (d)

(ii))

MOT #8 2020-03-18 13:10

MOT test number 684038987681

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Exhaust front flexi connection deteriorated

CarCheck.co.uk page 4/13



MOT #7 2020-03-17 11:08

MOT test number 113807263762

Result X Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

MOT #6 2019-03-09 16:20

MOT test number 466392152644

MOT #5 2019-03-09 12:10

MOT test number 837583243201

Result X Failed

Fail Offside Front Electrical wiring connectors for braking disconnected wear indicator wire (4.11 (a) (iii))

Fail Offside Front Headlamp aim too high (4.1.2 (a))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #4 2018-03-14 13:30

MOT test number 561095248004

Result
✓ Passed

Advice Water level on min

Advice Very light raised bit on both rear tyre inner side walls

CarCheck.co.uk page 5/13



 MOT #3
 2017-03-20 14:20

 MOT test number
 689707383634

 Result
 ✓ Passed

 MOT #2
 2017-03-16 15:39

 MOT test number
 602474639629

 Result
 X Failed

 Fail

 Nearside Rear Stop lamp not working (1.2.1b)

MOT #1	2016-02-29 11:45
MOT test number	630616031064
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	7 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-01
Last registration	2024-04-08
Complete history	See info



Registration #1	2013-03-01	15 mi
Registration #2	2016-02-29	24.738 mi
Registration #3	2017-03-16	34.591 mi
Registration #4	2017-03-20	34.592 mi
Registration #5	2018-03-14	52.588 mi
Registration #6	2019-03-09	60.967 mi
Registration #7	2019-03-09	60.967 mi
Registration #8	2020-03-17	70.016 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		0.00 44
Registration #15		D.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	1575 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13

Number of axles 2

Engine number 0596130