



KP57HFX

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE TDI (80BHP)
Colour	Grey
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption


Power	80 BHP
Max. torque	195 Nm at 2.200 rpm
Cylinders	3
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg





Internet history

Entry 1	
Date	2021-06-17
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #17</b>	2022-12-02 16:50
<b>MOT test number</b>	985441451182
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-12-03
<b>Advice</b>	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #16</b>	2022-12-02 13:36
<b>MOT test number</b>	935792391037
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Headlamp aim too low (4.1.2 (a))
<b>Fail</b>	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
<b>Fail</b>	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Fail</b>	Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
<b>Advice</b>	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
<b>Fail</b>	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
<b>Fail</b>	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

<b>MOT #15</b>	2021-11-13 11:53
<b>MOT test number</b>	648453958338
<b>Result</b>	✓ Passed



<b>MOT #14</b>	2021-11-13 11:53
<b>MOT test number</b>	199081574374
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Pass with rectification</b>	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

<b>MOT #13</b>	2020-12-04 09:24
<b>MOT test number</b>	652127273632
<b>Result</b>	✓ Passed

<b>MOT #12</b>	2020-12-04 09:24
<b>MOT test number</b>	578896365991
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

<b>MOT #11</b>	2019-11-11 09:40
<b>MOT test number</b>	261638891440
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2018-10-29 16:24
<b>MOT test number</b>	943926321335
<b>Result</b>	✓ Passed

<b>MOT #9</b>	2017-10-30 12:14
<b>MOT test number</b>	547385315049
<b>Result</b>	✓ Passed

**MOT #8** 2016-10-18 07:48**MOT test number** 189685282856**Result** ✓ Passed**Advice** Nearside Front worn on outer edge**MOT #7** 2015-11-10 10:57**MOT test number** 109975075500**Result** ✓ Passed**MOT #6** 2014-11-12 14:44**MOT test number** 456556614431**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Rear exhaust silencer corroded**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2013-11-04 09:03**MOT test number** 109388103397**Result** ✓ Passed**MOT #4** 2012-10-26 08:28**MOT test number** 139060002335**Result** ✓ Passed**MOT #3** 2011-11-18 12:55**MOT test number** 226532221346**Result** ✓ Passed



MOT #2	2011-11-18 10:55
MOT test number	265062021321
Result	✗ Failed
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Notice	N/s/f brake disc pitted

MOT #1	2011-01-05 09:05
MOT test number	987605101012
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-01-16
Last registration	2022-12-02
Complete history	<a href="#">See info</a>



Registration #1	2008-01-16	11 mi
Registration #2	2011-01-05	18.265 mi
Registration #3	2011-11-18	23.320 mi
Registration #4	2011-11-18	23.320 mi
Registration #5	2012-10-26	31.837 mi
Registration #6	2013-11-04	41.000 mi
Registration #7	2014-11-12	52.893 mi
Registration #8	2015-11-10	63.405 mi
Registration #9	2016-10-18	72.470 mi
Registration #10	2017-10-30	80.754 mi
Registration #11	2018-05-22	91.277 mi
Registration #12	2019-05-22	101.277 mi
Registration #13	2020-05-22	111.277 mi
Registration #14	2021-05-22	121.277 mi
Registration #15	2022-05-22	131.277 mi
Registration #16	2023-05-22	141.277 mi
Registration #17	2024-05-22	151.277 mi
Registration #18	2025-05-22	161.277 mi
Registration #19	2026-05-22	171.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

BNV115675