



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	HORIZON TEPEE S
Colour	Silver
Year of manufacture	2013
Top speed	110 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	164 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT expiry date	2025-04-16
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	35
Total items failed	1

MOT #13 2024-03-19 08:41**MOT test number** 330406890991**Result** Passed**Next expiry date** 2025-04-16**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated Weeping grease (6.1.7 (g) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #12** 2023-04-06 14:05**MOT test number** 359795458470**Result** Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11** 2023-04-06 14:05**MOT test number** 918112553139**Result** ✗ Failed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2022-04-12 09:46**MOT test number** 710330379764**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #9** 2021-04-17 10:54**MOT test number** 104124560814**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #8** 2021-04-16 16:38**MOT test number** 908121624344**Result** ✓ Passed**Advice** Coil spring corroded Both rear (5.3.1 (b) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))**MOT #7** 2020-06-29 09:22**MOT test number** 864755732483**Result** ✓ Passed**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**MOT #6** 2019-07-04 08:59**MOT test number** 873877958512**Result** ✓ Passed**Advice** Both front tyres getting low**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 0mm on outer edge (5.2.3 (e))**Advice** Offside rear tyre getting low**MOT #5** 2019-06-25 12:24**MOT test number** 348906725541**Result** ✗ Failed**Advice** Both front tyres getting low**MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Offside rear tyre getting low**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 0mm on outer edge (5.2.3 (e))

**MOT #4** 2018-06-14 10:07**MOT test number** 803014845511**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-06-13 12:16**MOT test number** 436630511829**Result** ✗ Failed**MAJOR** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2017-06-29 10:55**MOT test number** 772960099993**Result** ✓ Passed**MOT #1** 2016-07-25 12:56**MOT test number** 467088985988**Result** ✓ Passed**Advice** Rear Centre and nearside seat missing due to wheel chair conversion.



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
16 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	SG63WKM
Plate since	2019-09-28
Current registration	SG63WKM
Plate since	2019-09-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-25
Last registration	2024-03-19
Complete history	See info



Registration #1	2013-09-25	10 mi
Registration #2	2016-07-25	12.111 mi
Registration #3	2017-06-29	16.320 mi
Registration #4	2018-06-13	20.281 mi
Registration #5	2018-06-14	20.281 mi
Registration #6	2019-06-25	23.091 mi
Registration #7	2019-07-04	23.118 mi
Registration #8	2020-06-29	24.714 mi
Registration #9	2020-06-29	25.377 mi
Registration #10	2020-06-29	25.377 mi
Registration #11	2020-06-29	25.377 mi
Registration #12	2020-06-29	25.377 mi
Registration #13	2020-06-29	25.377 mi
Registration #14	2020-06-29	25.377 mi
Registration #15	2020-06-29	25.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	2112 mm
Height	1862 mm
Length	4380 mm
Wheel base	2728 mm
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

FHCM1885258