



report date: 2024-03-28

General information

Make	CITROEN
Model	DS5 HYBRID4 DSTYLE EGS
Colour	White
Year of manufacture	2014
Top speed	131 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Electric / Diesel
Consumption city	88.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	80.7 mpg
CO2 emission	102 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-23
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-12
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	10
Total items failed	5

MOT #8	2023-08-01 07:28
MOT test number	331287899824
Result	✓ Passed
Next expiry date	2024-08-12
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7	2022-08-11 08:08
MOT test number	475340967753
Result	✓ Passed

MOT #6	2021-08-09 07:49
MOT test number	724907501494
Result	✓ Passed

MOT #5	2020-08-13 16:35
MOT test number	478266989746
Result	✓ Passed
Advice	Lower windscreen cracked
Advice	Nearside Front Outer Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #4** 2020-08-07 10:57**MOT test number** 961079518455**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))**Minor** Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))**Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #3** 2019-03-21 16:10**MOT test number** 446571710795**Result** ✓ Passed**Advice** Slight movement int the os track rod end**MOT #2** 2018-03-15 11:26**MOT test number** 965611029894**Result** ✓ Passed**MOT #1** 2017-03-25 11:20**MOT test number** 826849285840**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
12 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	12 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 10,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 10,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>LX14XXS</b>
Plate since	2019-09-29
Current registration	<b>LX14XXS</b>
Plate since	2019-09-29

More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-03-26
Last registration	2023-08-01
Complete history	<a href="#">See info</a>



Registration #1	2014-03-26	26 mi
Registration #2	2017-03-25	28.408 mi
Registration #3	2018-03-15	51.044 mi
Registration #4	2019-03-21	72.948 mi
Registration #5	2020-08-07	102.487 mi
Registration #6	2021-03-22	121.277 mi
Registration #7	2022-03-22	131.277 mi
Registration #8	2023-03-22	141.277 mi
Registration #9	2024-03-22	151.277 mi
Registration #10	2025-03-22	161.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	83%
Pedestrian	40%
Safety systems	97%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1850 mm
Height	1508 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1740 kg
Max. allowed weight	2265 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYZC4055829