



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 FURIO
Colour	Silver
Year of manufacture	-
Top speed	105 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-12
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #12</b>	2020-10-07 17:02
<b>MOT test number</b>	800110098584
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-10-06
<b>Advice</b>	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
<b>Advice</b>	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Under body has general corrosion
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Front and rear suspension has general corrosion

<b>MOT #11</b>	2019-09-30 12:13
<b>MOT test number</b>	543291987987
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front winter tyre fitted
<b>Minor</b>	Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

<b>MOT #10</b>	2018-10-02 09:17
<b>MOT test number</b>	344122522193
<b>Result</b>	✓ Passed

**MOT #9** 2017-10-02 11:55**MOT test number** 615572497554**Result** ✓ Passed

- Advice** Offside Front Lower chassis damage but not structural
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #8** 2016-09-29 08:54**MOT test number** 255173480519**Result** ✓ Passed

- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #7** 2015-10-01 08:51**MOT test number** 192062346407**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front Tyre worn close to the legal limit both (4.1.E.1)

**MOT #6** 2014-10-02 14:02**MOT test number** 828805574263**Result** ✓ Passed**MOT #5** 2014-10-02 11:29**MOT test number** 638255474200**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Fail** Offside Rear Exhaust system not adequately supported (7.1.1)



<b>MOT #4</b>	2013-10-05 12:51
---------------	------------------

<b>MOT test number</b>	208418173251
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2012-08-13 15:51
---------------	------------------

<b>MOT test number</b>	118516622277
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2011-08-08 09:37
---------------	------------------

<b>MOT test number</b>	885580821269
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Front Shock absorber has a light misting of oil (2.7.3)
---------------	---

<b>MOT #1</b>	2010-08-04 19:08
---------------	------------------

<b>MOT test number</b>	810286210262
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Rear Brake pad(s) wearing thin (3.5.1g)
---------------	---



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	KX07CEE
Plate since	2019-03-29
Current registration	KX07CEE
Plate since	2019-03-29

More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-08-01
Last registration	2020-10-07
Complete history	<a href="#">See info</a>



Registration #1	2007-08-01	7 mi
Registration #2	2010-08-04	30.368 mi
Registration #3	2011-08-08	40.030 mi
Registration #4	2012-08-13	50.108 mi
Registration #5	2013-10-05	61.007 mi
Registration #6	2014-10-02	77.871 mi
Registration #7	2014-10-02	77.871 mi
Registration #8	2015-05-20	78.277 mi
Registration #9	2015-05-20	78.277 mi
Registration #10	2015-05-20	78.277 mi
Registration #11	2015-05-20	78.277 mi
Registration #12	2015-05-20	78.277 mi
Registration #13	2015-05-20	78.277 mi
Registration #14	2015-05-20	78.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1474 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	991 kg
Max. allowed weight	1362 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FST35740035