



report date: 2024-03-28

General information

| | |
|---------------------|-----------------------|
| Make | MINI |
| Model | PACEMAN COOPER D ALL4 |
| Colour | Red |
| Year of manufacture | 2014 |
| Top speed | 113 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 7 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 112 BHP |
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-30 |
| Pictures | 3 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-08 |
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 3 |
| Total items failed | 5 |

| | |
|------------------|--|
| MOT #7 | 2023-06-01 15:45 |
| MOT test number | 590795611786 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-08 |
| Advice | Central Front Upper ENGINE COVER FITTED NOT ALLOWING FULL INSPECTION |

| | |
|-----------------|------------------|
| MOT #6 | 2022-05-27 16:09 |
| MOT test number | 361714071934 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #5 | 2021-06-09 11:31 |
| MOT test number | 900396687473 |
| Result | ✓ Passed |

**MOT #4** 2021-06-08 14:16**MOT test number** 677485175512**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Reversing lamp inoperative (4.6.1 (a))**Fail** Offside Front Road wheel more than one fixing missing stud (5.2.1 (a) (ii))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Fail** Nearside Front Road wheel more than one fixing missing stud (5.2.1 (a) (ii))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2019-03-25 15:53**MOT test number** 789553390308**Result** ✓ Passed**MOT #2** 2018-04-09 13:33**MOT test number** 817142223185**Result** ✓ Passed**MOT #1** 2017-02-06 10:23**MOT test number** 420525859499**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
8 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 95 |
| MOT expiry date | 8 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MINI had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | GV63CJX |
| Plate since | 2019-09-29 |
| Current registration | GV63CJX |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2014-02-19 |
| Last registration | 2023-06-01 |
| Complete history | See info |



| | | |
|-----------------|------------|------------|
| Registration #1 | 2014-02-19 | 21 mi |
| Registration #2 | 2017-02-06 | 22.982 mi |
| Registration #3 | 2018-04-09 | 26.857 mi |
| Registration #4 | 2019-03-25 | 53.889 mi |
| Registration #5 | 2021-06-08 | 82.000 mi |
| Registration #6 | 2022-06-01 | 100.000 mi |
| Registration #7 | 2022-06-01 | 100.000 mi |
| Registration #8 | 2022-06-01 | 100.000 mi |
| Registration #9 | 2023-06-01 | 100.000 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 84% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1786 mm |
| Height | 1518 mm |
| Length | 4109 mm |
| Wheel base | 2596 mm |
| Kerb weight | 1370 kg |
| Max. allowed weight | 1840 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 47 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 4 |

| | |
|------------------------|----------|
| Number of axles | 2 |
| Engine number | 70048914 |