



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO DYNAMIC DUALOGIC
Colour	Grey
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	5.1 mpg
CO2 emission	124 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-01-21
Pictures	19
Listing price	View report



source: yesauto.com





MOT history

MOT expiry date	2024-09-24
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	37
Total items failed	5

MOT #13	2023-09-25 13:36
MOT test number	517055587403
Result	✓ Passed
Next expiry date	2024-09-24

MOT #12	2022-11-09 16:26
MOT test number	756285723490
Result	✓ Passed

MOT #11	2021-11-30 13:25
MOT test number	359198458442
Result	✓ Passed

MOT #10	2021-11-30 13:25
MOT test number	498074991100
Result	✗ Failed
Pass with rectification	Rear fog lamp not working (4.5.1 (a) (ii))



MOT #9	2020-12-02 15:47
MOT test number	179380367167
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8	2020-09-10 11:10
MOT test number	689078119900
Result	✓ Passed
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Exhaust system is corroded
Advice	Front Brake disc worn, but not excessively both (1.1.14 (a) (i))
Advice	Offside under floor cover obscuring some components
Advice	Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))

MOT #7	2020-09-09 13:35
MOT test number	841063053002
Result	✗ Failed
Advice	Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
Advice	Exhaust system is corroded
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Offside under floor cover obscuring some components
Advice	Front Brake disc worn, but not excessively both (1.1.14 (a) (i))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #6**

2019-09-11 10:55

MOT test number

657628216544

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))
- Advice** Rear Coil spring corroded offside & nearside (5.3.1 (b) (i))
- Advice** Engine oil sump is corroded
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened offside & nearside (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))
- Advice** Exhaust system is corroded

MOT #5

2019-09-10 10:23

MOT test number

993348218906

Result

✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Engine oil sump is corroded
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Coil spring corroded offside & nearside (5.3.1 (b) (i))
- Advice** Exhaust system is corroded
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened offside & nearside (1.1.14 (a) (ii))

**MOT #4** 2018-09-13 10:14**MOT test number** 503540697885**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear cracking**Advice** Offside Front Lower Coil spring corroded (5.3.1 (b) (i))**MOT #3** 2017-09-11 12:02**MOT test number** 821008288250**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #2** 2016-09-05 09:46**MOT test number** 749907647047**Result** ✓ Passed**Advice** Exhaust system is corroded**Advice** Under trays fitted obscuring some components



MOT #12015-09-14 11:04

MOT test number722898679635

Result✓ Passed

- Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice Offside wiper blade torn.
- Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice Treads on inner and outer edges of both front tyres breaking up.
- Advice Front valance moulding insecure.



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-09-15
Last registration	2023-09-25
Complete history	See info



Registration #1	2012-09-15	6 mi
Registration #2	2015-09-14	30.485 mi
Registration #3	2016-09-05	39.679 mi
Registration #4	2017-09-11	52.279 mi
Registration #5	2018-09-13	61.412 mi
Registration #6	2019-09-10	69.048 mi
Registration #7	2019-09-11	69.050 mi
Registration #8	2020-09-09	77.415 mi
Registration #9	2023-09-25	150.000 mi
Registration #10	2023-09-25	150.000 mi
Registration #11	2023-09-25	150.000 mi
Registration #12	2023-09-25	150.000 mi
Registration #13	2023-09-25	150.000 mi
Registration #14	2023-09-25	150.000 mi
Registration #15	2023-09-25	150.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6750825