



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Red
Year of manufacture	2008
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-02-23
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-05
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	23
Total items failed	13

MOT #20 2024-02-21 10:54

MOT test number 519244640681

Result ✓ Passed

Next expiry date 2025-03-05

Advice Front exhaust heat shield insecure .///

Advice Oil leak, but not excessive engine./// (8.4.1 (a) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #19 2024-02-20 12:30

MOT test number 219510843261

Result ✗ Failed

Advice Oil leak, but not excessive engine./// (8.4.1 (a) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Rear Spare wheel carrier insecure (6.1.5 (a))

Advice Front exhaust heat shield insecure .///

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure ./// (6.1.7 (g) (ii))

**MOT #18**

2023-03-06 14:42

MOT test number

326667011781

Result

✓ Passed

- Advice** Nearside Rear Nail in tyre
- Advice** Front exhaust heat shield insecure ///
- Advice** Oil leak, but not excessive engine /// (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on outer edge /// (5.2.3 (e))

MOT #17

2023-03-06 10:05

MOT test number

233450808531

Result

✗ Failed

- Fail** Offside Front Headlamp aim unable to be tested (4.1.2 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on outer edge /// (5.2.3 (e))
- Advice** Nearside Rear Nail in tyre
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Passenger's seat insecure (6.2.6 (a) (ii))
- Advice** Front exhaust heat shield insecure ///
- Advice** Oil leak, but not excessive engine /// (8.4.1 (a) (i))
- Advice** Spare tyre defective flat ///

MOT #16

2022-02-17 17:13

MOT test number

784821514174

Result

✓ Passed

**MOT #15** 2022-02-17 17:13**MOT test number** 794777494000**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #14** 2021-07-30 13:49**MOT test number** 246167186306**Result** ✓ Passed**MOT #13** 2020-07-23 10:07**MOT test number** 376646556451**Result** ✓ Passed**MOT #12** 2019-02-11 12:42**MOT test number** 965232452000**Result** ✓ Passed**MOT #11** 2019-02-07 16:38**MOT test number** 488366400793**Result** ✗ Failed**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords + low edges (5.2.3 (d) (i))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords + low edges (5.2.3 (d) (i))**MOT #10** 2017-11-02 10:54**MOT test number** 722684013793**Result** ✓ Passed**Advice** Oil leak**Advice** Screw in fuel tank but does not appear to be leaking

**MOT #9** 2017-11-02 10:54**MOT test number** 976851825391**Result** ✗ Failed**Advice** Screw in fuel tank but does not appear to be leaking**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Oil leak**MOT #8** 2016-10-27 15:16**MOT test number** 781505099156**Result** ✓ Passed**Advice** Fuel tank oily around drain plug?.**MOT #7** 2016-10-27 15:16**MOT test number** 480053399140**Result** ✗ Failed**Advice** Fuel tank oily around drain plug?.**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #6** 2015-07-09 10:15**MOT test number** 285960595179**Result** ✓ Passed**MOT #5** 2015-02-02 14:29**MOT test number** 175873935411**Result** ✓ Passed



MOT #4	2014-02-14 09:01
MOT test number	379465244057
Result	✓ Passed
Notice Both rear tyres starting to crack on sidewalls	

MOT #3	2013-02-22 12:10
MOT test number	716693453077
Result	✓ Passed

MOT #2	2012-02-20 10:17
MOT test number	726821452012
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2011-02-28 11:21
MOT test number	655809451043
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
5 March 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	5 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	DU08AEK
Plate since	2024-03-29
Current registration	DU08AEK
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-03-13
Last registration	2024-02-21
Complete history	See info



Registration #1	2008-03-13	27 mi
Registration #2	2011-02-28	20.287 mi
Registration #3	2012-02-20	27.505 mi
Registration #4	2013-02-22	34.818 mi
Registration #5	2014-02-14	38.830 mi
Registration #6	2015-02-02	43.297 mi
Registration #7	2015-07-09	50.473 mi
Registration #8	2016-10-27	59.920 mi
Registration #9	2016-10-27	59.920 mi
Registration #10	2017-11-02	66.816 mi
Registration #11	2017-11-02	66.816 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi
Registration #20	2019-05-29	75.277 mi
Registration #21	2019-05-29	75.277 mi
Registration #22	2019-05-29	75.277 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBAW0025049