





report date: 2024-03-28

General information

Make	BMW
Model	1 SERIES 320D SPORT TOURING
Colour	White
Year of manufacture	2013
Top speed	141 mph
0 - 60 mph	7.6 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	72.4 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/14



report date: 2024-03-28


Internet history

Entry 2


Date 2021-01-28

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1


Date 2021-01-22

Pictures 40

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-03-21
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	35
Total items failed	5

MOT #12		2024-03-22 13:50
MOT test	number	154795972214
Result		✓ Passed
Next expi	ry date	2025-03-21
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm & perishing 205/50x17 (5.2.3 (e))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm & perishing 205/50x17 (5.2.3 (e))		
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #11	2024-03-22 10:56	
MOT test number	962775279336	
Result	X Failed	
Fail Windscreen washer not working (3.5 (a))		
Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm & perishing 205/50x17 (5.2.3 (e))		
Fail Bonnet cannot be secured in the closed position (3.1 (b) (i))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm &	perishing 205/50x17 (5.2.3 (e))	

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #10

MOT test number

959090562896

Result

Advice

Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Minor

Windscreen damaged but not adversely affecting driver's view SMALL CHIPS (3.2 (a) (i))

MOT test number

482785428053

Result

Minor

Windscreen damaged but not adversely affecting driver's view SMALL CHIPS (3.2 (a) (i))

Advice

Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Fail

Windscreen washer not working (3.5 (a))

Fail

Offside Rear Service brake excessively binding (1.2.1 (f))

MOT #8 2022-02-24 14:29 738177188800 **MOT** test number Result Passed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge EDGE 205/50*17 (5.2.3 (e)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3MM 205/50*17 (5.2.3 (e)) **Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge EDGE 205/50*17 (5.2.3 (e)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3MM 205/50*17 (5.2.3 (e))

 MOT #7
 2021-01-25 10:58

 MOT test number
 803382319870

 Result
 ✓ Passed

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #6 2020-01-24 15:27

MOT test number 166967268508

1.101 (636	namber 100.	707200300
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Engine covers and under trays fitted not allowing full inspection	
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Valve stem slightly damaged BOTH (5.2.3 (j))	
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Rear Nail in tyre	
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Outer Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))	

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #5		2020-01-24 09:49
MOT test	number	221408112016
Result		× Failed
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Valve stem slightly damaged BOTH (5.2.3 (j))	
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1	.14 (a) (ii))
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Outer Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))	
Fail Fi	ront Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice	Nearside Rear Nail in tyre	
Advice	Engine covers and under trays fitted not allowing full inspection	
Advice	Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.	14 (a) (ii))

MOT #4	2019-01-23 14:28
MOT test number	800243654152
Result	✓ Passed
MOT #3	2018-02-23 13:16
MOT test number	843752653386
Result	✓ Passed
MOT #2	2017-02-21 08:30
MOT test number	105549231792
Result	✓ Passed

CarCheck.co.uk page 6/14



MOT #1 2016-04-12 09:36

MOT test number 190852825891

Result ✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	21 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>		ve?

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK LINE	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-05-02
Last registration	2024-03-22
Complete history	See info



Registration #1	2013-05-02	8 mi
Registration #2	2016-04-12	34.876 mi
Registration #3	2017-02-21	40.095 mi
Registration #4	2018-02-23	44.521 mi
Registration #5	2019-01-23	49.628 mi
Registration #6	2020-01-24	59.519 mi
Registration #7	2020-01-24	59.519 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1462 mm
Length	4624 mm
Wheel base	2810 mm
Kerb weight	1500 kg
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	57 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2

Engine number 82808376