





report date: 2024-03-28

General information

Make	JAGUAR
Model	XJS
Colour	Green
Year of manufacture	1995
Gearbox	4 speed automatic

Engine & fuel consumption

Engine capacity	3.980 cc
Fuel type	Petrol



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-06-17

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-03-04
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	40
Total items failed	3

MOT #12		2024-02-28 13:00
MOT test	number	571652332277
Result		✓ Passed
Next expi	ry date	2025-03-04
Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn inner ed	ge (5.2.3 (e))

MOT #11	2023-02-23 15:45
MOT test number	337124262154
Result	✓ Passed
MOT #10	2022-02-14 16:30
MOT test number	826928688692
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #9 2021-02-26 12:32

MOT test number 836880102321

Result
✓ Passed

Advice Rear Coil spring corroded all coil spring (5.3.1 (b) (i))

Advice Nearside Front Fuel Pipe/s corroded

Advice Front Coil spring corroded both (5.3.1 (b) (i))

Advice Offside Rear Exhaust mounting defective clamp (6.1.2 (a))

MOT #8 2020-03-05 14:14

MOT test number 517831571947

Result \(\sqrt{Passed} \)

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))

Advice Rear general corrosion on suspension and sub-frame

Advice Offside Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Outer Tyre slightly damaged/cracking or perishing wall perishing (5.2.3 (d) (ii))

Advice Front general corrosion on suspension and sub-frame

Advice Nearside Front Lower fuel pipe corroded next to chassis

CarCheck.co.uk page 4/13



MOT #7 2020-03-03 16:31

MOT test number 470694965646

Result X Failed

Fail Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure wall (5.2.3 (d) (ii))

Advice Front general corrosion on suspension and sub-frame

Advice Offside Rear Outer Tyre slightly damaged/cracking or perishing wall perishing (5.2.3 (d) (ii))

Advice Nearside Front Lower fuel pipe corroded next to chassis

Advice Offside Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Inner Tyre slightly damaged/cracking or perishing wall perishing (5.2.3 (d) (ii))

Advice Rear general corrosion on suspension and sub-frame

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement front

(5.3.4 (a) (i))

MOT #6 2018-07-23 11:53

MOT test number 791246373189

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 5/13



Advice

M988JKV

report date: 2024-03-28

MOT #5	2011-07-18 13:46
MOT test	number 707319491102
Result	✓ Passed
Advice (2.4.G.2)	Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement
Advice	Offside Body has slight corrosion (6.1.B.2)
Notice	Subframe corroded
Advice	Offside Front coil spring corroded (2.4.C.1b)
Advice	Offside Rear coil spring corroded (2.4.C.1b)
Advice (2.4.G.2)	Offside Front Sub-frame rubber bush deteriorated but not resulting in excessive movement
Advice	Nearside Body has slight corrosion (6.1.B.2)
Advice	Nearside Front coil spring corroded (2.4.C.1b)

MOT #4		2010-03-26 12:27
MOT test	number	182345380019
Result		√ Passed
Notice	N/s/f tyre has perrishing	
Notice	Fuel pipes have slight corrosion	
Advice	Nearside Front wheel bearing has slight play (2.5.A.3c)	
Notice	All brake pipes have slight corrosion	
Notice	Floor pan near to jackin points have corrosion	
Advice	Offside Front wheel bearing has slight play (2.5.A.3c)	

Nearside Rear coil spring corroded (2.4.C.1b)

CarCheck.co.uk page 6/13



MOT #3 2010-03-26 12:27 832795080015 **MOT test number** Result × Failed **Notice** Fuel pipes have slight corrosion Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) Advice Nearside Front wheel bearing has slight play (2.5.A.3c) Notice All brake pipes have slight corrosion Notice Floor pan near to jackin points have corrosion Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Offside Front wheel bearing has slight play (2.5.A.3c) Notice N/s/f tyre has perrishing

MOT #2	2007-06-22 17:22
MOT test number	154183577171
Result	✓ Passed

MOT #1	2006-07-19 12:36
MOT test number	421570706284
Result	✓ Passed

CarCheck.co.uk page 7/13







Days left 126

MOT expiry date 4 March 2025

Full MOT history See MOT history

CarCheck.co.uk page 8/13



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/13



M988JKV

report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 10/13



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	1995-02-22
Last registration	2024-02-28
Complete history	See info



Registration #1	1995-02-22	11 mi
Registration #2	2006-07-19	56.252 mi
Registration #3	2007-06-22	56.870 mi
Registration #4	2010-03-26	56.968 mi
Registration #5	2011-07-18	56.992 mi
Registration #6	2018-07-23	57.002 mi
Registration #7	2020-03-03	57.087 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		10,177 mg

More info >

CarCheck.co.uk page 12/13



Additional information

Engine number 9LPFRB133215

CarCheck.co.uk page 13/13