



report date: 2024-03-29

General information

| | |
|---------------------|-----------------------------------|
| Make | VAUXHALL |
| Model | COMBO L1H1 2000 SPORTIVE CDTI S/S |
| Colour | White |
| Year of manufacture | 2017 |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|----------|
| Power | 94 BHP |
| Engine capacity | 1.248 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 52.3 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 120 g/km |
| CO2 label | C |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-29 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2024-09-20 |
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 15 |
| Total items failed | 0 |

MOT #5 2023-09-07 15:45**MOT test number** 314881241521**Result** Passed**Next expiry date** 2024-09-20

- Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner Edge Worn Smooth (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Central Front Lower Gearbox mounting defective Dog Bone Mounting Bush Worn
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner Edge Worn Smooth (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #4 2022-09-21 14:57**MOT test number** 736389254649**Result** Passed

- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #3** 2021-09-14 15:34**MOT test number** 208805190111**Result** ✓ Passed**MOT #2** 2020-08-03 08:41**MOT test number** 388255872013**Result** ✓ Passed**MOT #1** 2020-07-14 10:48**MOT test number** 149872164411**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
20 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 185 |
| MOT expiry date | 20 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|----------------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  FJ17WVH |
| Plate since | 2019-03-29 |
| Current registration |  FJ17WVH |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 7 |
| First mileage registration | 2017-03-21 |
| Last registration | 2023-09-07 |
| Complete history | See info |



| | | |
|-----------------|------------|------------|
| Registration #1 | 2017-03-21 | 24 mi |
| Registration #2 | 2020-07-14 | 61.799 mi |
| Registration #3 | 2020-08-03 | 61.800 mi |
| Registration #4 | 2021-09-14 | 83.169 mi |
| Registration #5 | 2023-09-07 | 105.277 mi |
| Registration #6 | 2023-09-07 | 105.277 mi |
| Registration #7 | 2023-09-07 | 105.277 mi |

More info >



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2119 mm |
| Height | 1845 mm |
| Length | 4390 mm |
| Kerb weight | 1290 kg |
| Max. allowed weight | 2040 kg |

Additional information

| | |
|--------------------|---------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 2 |
| Engine number | 330A10006219112 LN9 |