





report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2013
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E



CarCheck.co.uk page 1/10



MOT history

MOT expiry date	2024-04-14
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	17
Total items failed	5

MOT #4	2023-04-14 07:13
MOT test number	464476915589
Result	✓ Passed
Next expiry date	2024-04-14

MOT #3	2022-03-31 10:48
MOT test number	817735401824
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Offside Front Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #2	2021-04-15 11:32
MOT test number	942352072523
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Advice Front registration plate damaged but not likely to be misread	

CarCheck.co.uk page 2/10



GF13VXR

report date: 2024-03-29

MOT #1 2021-03-31 10:41

MOT test number 982804391112

Result × Failed

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Rear exhaust rubber deteriorated / split

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front registration plate damaged but not likely to be misread

Fail Nearside Rear Brake cable damaged handbrake cable (1.1.15 (a))

Advice N/s door mirror casing missing

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Centre exhaust rubber missing

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Noise from both front suspension top mount areas whilst going lock to lock

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice N/s/r light lens damaged

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice N/s and o/s side repeater len's damaged

CarCheck.co.uk page 3/10



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	14 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



GF13VXR

More info >

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

THE STREET	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	ZIS UK
Plate since	
Europeal regulatration	NIE.
Carrent region and	UK UK
Plate since	ÜK (

CarCheck.co.uk page 7/10



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2013-07-05
Last registration	2023-04-14
Complete history	See info



Registration #1	2013-07-05	10 mi
Registration #2	2021-03-31	71.112 mi
Registration #3	2021-04-15	71.114 mi
Registration #4		71.777 44
Registration #5		11.777 es

More info >

CarCheck.co.uk page 9/10



GF13VXR

report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	4945767

CarCheck.co.uk page 10/10