





### General information

Make	BMW
Model	530 535D M SPORT TOURING
Colour	Grey
Year of manufacture	2011
Gearbox	8 speed automatic

# Engine & fuel consumption

Power	299 BHP	0 < 101 A
Engine capacity	2.993 cc	101 - 120 <sup>B</sup> <sub>C</sub>
Cylinders	6	121 - 140 E
Fuel type	Diesel	141 - 165 F G
CO2 emission	165 g/km	166 - 185 H
CO2 label	G	186 - 225 J
		225+ L





## Internet history

Entry	1
Date	

2022-01-25

20

Listing price

Pictures

View report









source: autotrader.co.uk



## MOT history

MOT expiry date	2025-01-25
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	13
Total items failed	10

MOT #15	2024-01-26 10:46
MOT test number	448764036008
Result	✓ Passed
Next expiry date	2025-01-25

MOT #1	14 2024-01-22	13:05
MOT te	est number 6172051	98612
Result	×	Failed
Fail (ii))	Nearside Front Tyre has a lump, caused by separation or partial failure of its structure x2 (5.2.3	(d)
Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))		(ii))
Fail Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))		))
<b>Fail</b> (5.2.3 (	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (d) (i))	

MOT #13	2023-01-26 11:27
MOT test number	662092330885
Result	Passed
Advice Nearside Front Lower Suspension arm ball joint has slight play Forwar	rd. (5.3.4 (a) (i))





MOT #12	2023-01-17 12:27
MOT test number	585247759172
Result	🗙 Failed
FailOffside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))AdviceNearside Front Lower Suspension arm ball joint has slight play Forward. (5.	3.4 (a) (i))

MOT #11	2022-01-24 15:28
MOT test number	389563462730
Result	🗸 Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (	1.1.14 (a) (ii))

MOT #10	2022-01-19 15:48
MOT test number	212093236769
Result	🗙 Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))   Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	ii))
Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	"))

MOT #9	2021-02-23 16:24
MOT test number	975040366893
Result	✓ Passed
<b>Advice</b> Offside Front Brake disc worn, pitted or scored, but not seriously inner face of disc (1.1.14 (a) (ii))	weakened Worn and pitted on
<b>Advice</b> Nearside Front Brake disc worn, pitted or scored, but not seriously inner face of disc (1.1.14 (a) (ii))	y weakened Worn and pitted on

MOT #8	2020-03-13 11:06
MOT test number	106527055445
Result	🗸 Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	





MOT #7	2020-03-12 13:01
MOT test number	744276328021
Result	🗙 Failed
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	ii))
<b>Fail</b> Nearside Front Lower Suspension arm ball joint excessively worn Rearmost (5.3.4 (	a) (i))
Fail Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
<b>Fail</b> Offside Front Lower Suspension arm ball joint excessively worn Rearmost (5.3.4 (a)	) (i))

MOT #6	2019-03-13 15:13
MOT test number	916592878607
Result	✓ Passed
MOT #5	2018-02-16 09:29
MOT test number	893807502974
Result	✓ Passed
MOT #4	2017-03-13 09:21
MOT test number	549725267478
Result	✓ Passed
Advice Nearside Rear Nail in tyre	
MOT #3	2016-03-02 11:14
MOT test number	164396855223
Result	✓ Passed





MOT #2		2015-03-09 10:13
MOT test nu	mber	728328165037
Result		✓ Passed
<b>Notice</b> U	nder-trays fitted obscuring some underside components	
MOT #1		2014-03-13 09:07
MOT test nu	mber	169402574091
Result		✓ Passed
<b>Notice</b> E	ngine covers fitted obscuring some components in the engine bay	
<b>Notice</b> U	nder-trays fitted obscuring some underside components	



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 25 January 2025
Tax status	Valid until 1 December
Days left	215
MOT expiry date	25 January 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE CO
Category	 Lashe
Туре	
Damage 2	AMPLE
Damage 2	e e et al
Date	 1.
Category	 AMP
Туре	

#### Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

Nonese and American Ame	
*************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this BMW had different number plate	S.
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-15
Last registration	2024-01-26
Complete history	See info



Registration #1	2011-03-15	29 mi
Registration #2	2014-03-13	25.429 mi
Registration #3	2015-03-09	32.560 mi
Registration #4	2016-03-02	41.846 mi
Registration #5	2017-03-13	49.232 mi
Registration #6	2018-02-16	60.109 mi
Registration #7	2019-03-13	72.863 mi
Registration #8	2020-03-12	85.162 mi
Registration #9	2020-03-13	85.162 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.277 mi
Registration #17		10.207 est





### Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
60569	

## Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	2102 mm
Height	1462 mm
Length	4907 mm
Wheel base	2968 mm
Kerb weight	1840 kg
Max. allowed weight	2490 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number Carcheck.co.uk	36877884 page 13/13