



KY6IOWX

report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT SZ2
Colour	Black
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-21
Pictures	8
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-09-04
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	20
Total items failed	4

MOT #12	2023-09-01 09:07
MOT test number	606626365916
Result	✓ Passed
Next expiry date	2024-09-04
Advice	Washers poor

MOT #11	2023-09-01 09:07
MOT test number	376998867072
Result	✗ Failed
Pass with rectification	Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
Advice	Washers poor

MOT #10	2022-08-31 08:11
MOT test number	517373945266
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material both rear to flexi hoses starting to corrode (1.1.11 (c))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9** 2021-08-28 09:23**MOT test number** 862628256904**Result** ✓ Passed**Advice** Nearside Front washer not working**MOT #8** 2020-09-01 09:52**MOT test number** 852363600409**Result** ✓ Passed**MOT #7** 2019-08-31 09:12**MOT test number** 913110461482**Result** ✓ Passed**Advice** Rear Nail in tyre both tyres**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Parking brake lever has slight travel, requires adjustment**MOT #6** 2018-09-04 09:17**MOT test number** 388837349056**Result** ✓ Passed**Advice** Handbrake lever long travel**Advice** Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))**Advice** Play in steering rack inner joint(s)**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #5** 2018-09-04 09:17**MOT test number** 268014502613**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Play in steering rack inner joint(s)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Handbrake lever long travel**MOT #4** 2017-09-01 08:45**MOT test number** 496983542020**Result** ✓ Passed**MOT #3** 2016-09-01 10:28**MOT test number** 977189688724**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2015-08-27 13:08**MOT test number** 414339315405**Result** ✓ Passed**MOT #1** 2014-09-05 12:13**MOT test number** 888528744222**Result** ✓ Passed**Notice** All tyres wearing



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
4 September 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	4 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	KY61OWX
Plate since	2019-09-28
Current registration	KY61OWX
Plate since	2019-09-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-01
Last registration	2023-09-01
Complete history	See info



Registration #1	2011-09-01	9 mi
Registration #2	2014-09-05	24.444 mi
Registration #3	2015-08-27	35.491 mi
Registration #4	2016-09-01	48.614 mi
Registration #5	2017-09-01	63.388 mi
Registration #6	2018-09-04	74.755 mi
Registration #7	2018-09-04	74.755 mi
Registration #8	2019-09-01	75.000 mi
Registration #9	2020-09-01	75.000 mi
Registration #10	2021-09-01	75.000 mi
Registration #11	2022-09-01	75.000 mi
Registration #12	2023-09-01	75.000 mi
Registration #13	2024-03-28	75.000 mi
Registration #14	2024-03-28	75.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1065 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1354225