



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	-
Top speed	130 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	175 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-07-04
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 1

Date	2021-07-03
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk

**MOT history**

<b>MOT #16</b>	2021-12-14 17:33
<b>MOT test number</b>	424509077033
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-12-13
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #15</b>	2020-12-08 16:49
<b>MOT test number</b>	494744806505
<b>Result</b>	✓ Passed

<b>MOT #14</b>	2020-11-30 16:36
<b>MOT test number</b>	350335703052
<b>Result</b>	✗ Failed
<b>Fail</b>	Headlamp aim projected beam image is obviously incorrect both (4.1.2 (c))
<b>Advice</b>	Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))
<b>Advice</b>	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
<b>Fail</b>	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Minor</b>	Indicator switch faulty (4.4.2 (a) (i))
<b>Fail</b>	Nearside Upper Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Fail</b>	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
<b>Advice</b>	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
<b>Fail</b>	Fuel cap/sealing device ineffective (6.1.3 (b) (i))

<b>MOT #13</b>	2020-02-11 18:01
<b>MOT test number</b>	747234076019
<b>Result</b>	✓ Passed

**MOT #12** 2019-02-06 12:46**MOT test number** 468251520915**Result** ✓ Passed**Advice** Road wheel slightly distorted both front (5.2.2 (c) (i))**Advice** Non obligatory mirror damaged both door mirrors**MOT #11** 2019-02-06 10:04**MOT test number** 390745406345**Result** ✗ Failed**Fail** Headlamp aim projected beam image is obviously incorrect nearside and offside (4.1.2 (c))**Advice** Road wheel slightly distorted both front (5.2.2 (c) (i))**Advice** Non obligatory mirror damaged both door mirrors**Fail** Nearside Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))**Fail** Headlamp aim not tested (4.1.2 (b))**MOT #10** 2018-01-26 09:04**MOT test number** 950488747495**Result** ✓ Passed**Advice** Both door mirrors damaged.**MOT #9** 2017-02-09 11:34**MOT test number** 587228362575**Result** ✓ Passed**MOT #8** 2016-02-08 13:11**MOT test number** 115435907056**Result** ✓ Passed



<b>MOT #7</b>	2015-02-16 10:44
---------------	------------------

<b>MOT test number</b>	248367045065
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2014-02-19 10:56
---------------	------------------

<b>MOT test number</b>	648490754047
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Rear Brake pad(s) wearing thin (3.5.1g)
---------------	---

<b>MOT #5</b>	2013-05-20 15:32
---------------	------------------

<b>MOT test number</b>	716970543112
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2012-05-25 09:54
---------------	------------------

<b>MOT test number</b>	668156742164
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2011-06-03 09:34
---------------	------------------

<b>MOT test number</b>	238424951451
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Ochunk out of n/s/r tyre.no cords exposed
---------------	---

<b>Notice</b>	Chunk out of n/s/f sidewall.no cords exposed
---------------	--

<b>MOT #2</b>	2010-06-10 11:53
---------------	------------------

<b>MOT test number</b>	341991360156
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #1	2010-06-10 11:53
MOT test number	264221860140
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Pass with rectification	Offside Headlamp aim too low (1.8)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 LD57OHT
Plate since	2019-06-29
Current registration	 LD57OHT
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-29
Last registration	2021-12-14
Complete history	<a href="#">See info</a>



Registration #1	2007-09-29	22 mi
Registration #2	2010-06-10	10.449 mi
Registration #3	2011-06-03	13.326 mi
Registration #4	2012-05-25	14.821 mi
Registration #5	2013-05-20	17.224 mi
Registration #6	2014-02-19	18.636 mi
Registration #7	2015-02-16	20.538 mi
Registration #8	2016-02-08	21.892 mi
Registration #9	2017-02-09	28.999 mi
Registration #10	2018-02-09	35.377 mi
Registration #11	2019-02-09	41.755 mi
Registration #12	2020-02-09	48.133 mi
Registration #13	2021-02-09	54.511 mi
Registration #14	2022-02-09	60.889 mi
Registration #15	2023-02-09	67.267 mi
Registration #16	2024-02-09	73.645 mi
Registration #17	2025-02-09	80.023 mi
Registration #18	2026-02-09	86.401 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1335 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	20KG9530