



General information

Make	MINI
Model	MINI COOPER
Colour	Black
Year of manufacture	2010
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-23
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-15
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	23
Total items failed	3

MOT #13	2023-06-06 13:27
MOT test number	969827711925
Result	✓ Passed
Next expiry date	2024-06-15
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Seat belt buckle slightly damaged buckle casing missing but still works ok (7.1.2 (d))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12**

2023-06-06 13:27

MOT test number

132138038278

Result**✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))
- Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Rear Seat belt buckle slightly damaged buckle casing missing but still works ok (7.1.2 (d))

MOT #11

2022-06-16 13:57

MOT test number

158300207792

Result**✓ Passed**

- Advice** Nearside Rear Seat belt stork casing damaged
- Advice** Front Exhaust flexi joint in poor condition
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Coolant level low

**MOT #10** 2021-05-06 10:04**MOT test number** 916343749578**Result** ✓ Passed

- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #9 2020-01-14 11:10**MOT test number** 863367185443**Result** ✓ Passed**MOT #8** 2018-11-02 15:57**MOT test number** 910362213713**Result** ✓ Passed**MOT #7** 2018-04-24 10:50**MOT test number** 477985448466**Result** ✓ Passed**MOT #6** 2017-12-08 11:48**MOT test number** 804465366068**Result** ✓ Passed**MOT #5** 2017-12-08 11:48**MOT test number** 218985106907**Result** ✗ Failed

- Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)



MOT #4	2016-11-11 13:32
MOT test number	744108906728
Result	✓ Passed
MOT #3	2015-11-24 11:33
MOT test number	372021199765
Result	✓ Passed
MOT #2	2014-12-09 11:23
MOT test number	378393244328
Result	✓ Passed
<div>NoticeOil leak</div>	
MOT #1	2013-11-28 11:41
MOT test number	708832633341
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
15 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	15 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-12-09
Last registration	2023-06-06
Complete history	See info



Registration #1	2010-12-09	20 mi
Registration #2	2013-11-28	30.794 mi
Registration #3	2014-12-09	41.307 mi
Registration #4	2015-11-24	52.885 mi
Registration #5	2016-11-11	59.975 mi
Registration #6	2017-12-08	66.716 mi
Registration #7	2017-12-08	66.716 mi
Registration #8	2018-04-24	68.270 mi
Registration #9	2019-05-20	70.377 mi
Registration #10	2019-05-20	70.377 mi
Registration #11	2019-05-20	70.377 mi
Registration #12	2019-05-20	70.377 mi
Registration #13	2019-05-20	70.377 mi
Registration #14	2019-05-20	70.377 mi
Registration #15	2019-05-20	70.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1165 kg
Max. allowed weight	1595 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2

Engine number

B177I731