



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 SW S
Colour	Black
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.397 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2024-01-17
Pictures	17
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-03
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-27
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	43
Total items failed	12

MOT #15 2023-09-12 12:14

MOT test number 984259593228

Result ✓ Passed

Next expiry date 2024-09-27

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14 2022-09-28 09:17

MOT test number 672986171849

Result ✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #13 2021-08-07 09:45

MOT test number 260274935196

Result ✓ Passed

Advice Underneath of vehicle has been undersealed

**MOT #12** 2021-08-07 09:45**MOT test number** 391091337710**Result** ✗ Failed**Advice** Underneath of vehicle has been undersealed**Pass with rectification** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Pass with rectification** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #11** 2020-12-10 09:21**MOT test number** 833547647939**Result** ✓ Passed**MOT #10** 2019-12-07 16:20**MOT test number** 484945027087**Result** ✓ Passed**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-12-15 14:12**MOT test number** 689442343311**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Wheel trim fitted to nearside rear and offside rear wheel**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8**

2018-12-08 10:00

MOT test number

874990310274

Result**✗ Failed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Wheel trim fitted to nearside rear and offside rear wheel**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #7**

2017-12-20 17:29

MOT test number

600387216357

Result**✓ Passed****Advice** Wheel trim fitted to nearside front, nearside rear and offside rear wheel**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Exhaust has a rear mounting broken away**Advice** Nearside Front Tyre worn close to the legal limit 2.28mm (4.1.E.1)

**MOT #6**

2017-12-20 10:24

MOT test number

975514650989

Result**✗ Failed****Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Wheel trim fitted to nearside front, nearside rear and offside rear wheel**Advice** Nearside Front Tyre worn close to the legal limit 2.28mm (4.1.E.1)**Fail** Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Exhaust has a rear mounting broken away**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #5**

2016-10-14 16:16

MOT test number

629792959190

Result**✓ Passed****Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Wheel trim fitted to each wheel**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4**

2016-10-14 12:43

MOT test number

607530830743

Result**✗ Failed****Fail** Exhaust system not adequately supported (7.1.1)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Wheel trim fitted to each wheel**MOT #3**

2015-09-01 00:00

MOT test number

172088133830

Result**✓ Passed****Advice** Brake disc worn, pitted or scored, but not seriously weakened offside and nearside front (3.5.1i)**Advice** Offside and nearside rear tyre cracked**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2**

2014-06-25 10:45

MOT test number

806376974150

Result**✓ Passed**



MOT #1	2013-06-17 16:11
MOT test number	678058163125
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Nail in nearside rear tyre



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
27 September 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	27 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-06
Last registration	2023-09-12
Complete history	See info



Registration #1	2010-05-06	9 mi
Registration #2	2013-06-17	41.292 mi
Registration #3	2014-06-25	30.737 mi
Registration #4	2015-09-01	39.388 mi
Registration #5	2016-10-14	46.699 mi
Registration #6	2016-10-14	46.699 mi
Registration #7	2017-12-20	52.683 mi
Registration #8	2017-12-20	52.683 mi
Registration #9	2018-12-08	58.287 mi
Registration #10	2019-05-29	59.377 mi
Registration #11	2019-05-29	59.377 mi
Registration #12	2019-05-29	59.377 mi
Registration #13	2019-05-29	59.377 mi
Registration #14	2019-05-29	59.377 mi
Registration #15	2019-05-29	59.377 mi
Registration #16	2019-05-29	59.377 mi
Registration #17	2019-05-29	59.377 mi
Registration #18	2019-05-29	59.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1972 mm
Height	1555 mm
Length	4149 mm
Wheel base	2540 mm
Kerb weight	1279 kg
Max. allowed weight	1691 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FGAJ0777174