





report date: 2024-03-28

General information

Make	BMW
Model	530 530D M SPORT
Colour	Black
Year of manufacture	2008
Top speed	154 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	235 BHP
Max. torque	500 Nm at 3.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.8 mpg
CO2 emission	176 g/km
CO2 label	I



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date 2021-10-03

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-05-18
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	35
Total items failed	10

MOT #17		2023-05-19 14:48
MOT test	number	147939921784
Result		✓ Passed
Next expi	ry date	2024-05-18
Advice	Seat belt flexible stalk missing, centre	
Advice	Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))	
Advice	Advice Offside Rear Upper Suspension arm ball joint has slight play rear (5.3.4 (a) (i))	
Advice	Advice Nearside Rear Inner Road wheel slightly distorted rim (5.2.2 (c) (i))	
Advice	Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Oil level low	
Advice	Power steering pipe/hose has slight seepage at joint to column (2.1.5 (a))	

CarCheck.co.uk page 3/15



MOT #16 2023-05-11 08:41

MOT test number 925287063606

Result X Failed

Fail Offside Headlamp aim too low (4.1.2 (a))

Fail Offside Front Headlamp levelling device inoperative (4.1.5 (a))

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Oil level low

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Advice Nearside Rear Inner Road wheel slightly distorted rim (5.2.2 (c) (i))

Advice Power steering pipe/hose has slight seepage at joint to column (2.1.5 (a))

Advice Offside Rear Upper Suspension arm ball joint has slight play rear (5.3.4 (a) (i))

Advice Seat belt flexible stalk missing, centre

MOT #15 2022-03-31 15:44

MOT test number 141255236667

MOT #14 2021-02-03 13:57

MOT test number 975813023208

Result ✓ Passed

Advice Offside Rear Brake cable damaged but not to excess Rubbing on half shaft (1.1.15 (a))

CarCheck.co.uk page 4/15



MOT #13 2021-01-20 12:33

MOT test number 441704220231

Result X Failed

Fail Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))

Advice Offside Rear Brake cable damaged but not to excess Rubbing on half shaft (1.1.15 (a))

Fail Offside Front Side repeater not working (4.4.1 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #12 2019-04-10 14:23

MOT test number 438993590240

Result ✓ Passed

MOT #11 2019-04-08 10:41

MOT test number 877508309661

Result X Failed

Fail Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

MOT #10 2018-03-15 17:42

MOT test number 137088514470

Result

Passed

MOT #9 2016-08-30 09:27

MOT test number 775493303195

Result ✓ Passed

CarCheck.co.uk page 5/15



MOT test number

Result

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT test number

S49661395026

Result

Notice Under-trays fitted obscuring some underside components

Notice N/s/f and o/s/f tyres showing signs of cracking between treads

Notice Engine covers fitted obscuring some components in the engine bay

MOT test number
956781895048

Result
Notice Engine covers fitted obscuring some components in the engine bay

Pass with rectification Offside Front Headlamp aim too far to the right (1.8)

Notice Under-trays fitted obscuring some underside components

Notice N/s/f and o/s/f tyres showing signs of cracking between treads

CarCheck.co.uk page 6/15



MOT #5 2014-03-31 12:13

MOT test number 186640894082

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components

Advice Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Offside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #4 2013-04-17 15:54

MOT test number 515597903121

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

MOT #3 2013-04-17 10:06

MOT test number 925417003173

Result × Failed

Fail Nearside Side repeater not working (1.4.A.2c)

Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)

Notice Under-trays fitted obscuring some underside components

Fail Nearside Track rod end ball joint has excessive play (2.2.B.1f)

Notice Engine covers fitted obscuring some components in the engine bay

CarCheck.co.uk page 7/15



MOT #2

MOT test number

Result

Notice
Under-trays fitted obscuring some underside components

Notice
Engine covers fitted obscuring some components in the engine bay

MOT #1

MOT test number

648536031141

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	18 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

For how long did the current and previous owner(s) have this BMW? How many owners did check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	mm.m.m
Current registration	SIE UK
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into


More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-06-25
Last registration	2023-05-19
Complete history	See info



Registration #1	2008-06-25	18 mi
Registration #2	2011-05-16	23.496 mi
Registration #3	2012-04-27	29.078 mi
Registration #4	2013-04-17	35.323 mi
Registration #5	2013-04-17	35.326 mi
Registration #6	2014-03-31	41.030 mi
Registration #7	2015-04-01	46.858 mi
Registration #8	2015-08-18	47.432 mi
Registration #9	2016-08-30	52.563 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.117 es

More info >

CarCheck.co.uk page 14/15



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1469 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1675 kg
Max. allowed weight	2160 kg

Additional information

· · · · · · · · · · · · · · · · · · ·		
Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 15/15