



General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Black
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-09-30
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-02-05
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-17
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	39
Total items failed	10

MOT #182023-07-18 14:48

MOT test number181330957975

Result✓ Passed

Next expiry date2024-07-17

- Advice** Nearside Play in steering rack inner joint(s)
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))

**MOT #17**

2023-07-13 15:50

MOT test number

675701994653

Result

✗ Failed

- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Play in steering rack inner joint(s)
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))
- Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Offside Headlamp aim unable to be tested (4.1.2 (b))

MOT #16

2022-08-10 14:03

MOT test number

480707545321

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))
- Advice** Nearside Play in steering rack inner joint(s)
- Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #15**

2022-08-10 14:03

MOT test number

475608589048

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**Advice** Nearside Play in steering rack inner joint(s)**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))**Pass with rectification** Offside Front Direction indicator not working (4.4.1 (a) (ii))**MOT #14**

2021-08-19 08:27

MOT test number

519644872419

Result

✓ Passed

MOT #13

2018-09-18 11:13

MOT test number

377901291135

Result

✓ Passed

Advice Nearside Front Play in steering rack inner joint(s)**MOT #12**

2017-10-04 07:41

MOT test number

831706075917

Result

✓ Passed

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit on 3mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit on 3mm (4.1.E.1)

**MOT #11** 2017-10-04 07:41**MOT test number** 898644726431**Result** ✗ Failed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit on 3mm (4.1.E.1)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit on 3mm (4.1.E.1)**MOT #10** 2016-10-27 13:06**MOT test number** 763190958583**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2015-10-30 13:24**MOT test number** 762646255544**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Engine cover fitted

**MOT #8** 2014-10-28 10:40**MOT test number** 317591504359**Result** ✓ Passed

- Notice** Rear number plate deteriorating
- Notice** Both rear tyres deteriorating,splitting and getting low
- Notice** Front and rear brake discs lipped
- Notice** Both front tyres getting very low

MOT #7 2014-10-28 10:40**MOT test number** 418211404410**Result** ✗ Failed

- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Notice** Front and rear brake discs lipped
- Notice** Both front tyres getting very low
- Notice** Rear number plate deteriorating
- Notice** Both rear tyres deteriorating,splitting and getting low

MOT #6 2013-10-19 10:42**MOT test number** 415342993282**Result** ✓ Passed**MOT #5** 2013-10-17 13:01**MOT test number** 796580993240**Result** ✗ Failed

- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)



MOT #4	2012-10-02 10:15
MOT test number	777536972249
Result	✓ Passed
MOT #3	2011-10-07 10:12
MOT test number	935990981296
Result	✓ Passed
MOT #2	2011-10-07 10:12
MOT test number	606000381282
Result	✗ Failed
<div>Pass with rectification</div> Offside Headlamp aim too high and too far to the right. (1.8)	
MOT #1	2010-10-08 12:16
MOT test number	240661580242
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
17 July 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	17 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-10-10
Last registration	2023-07-18
Complete history	See info



Registration #1	2007-10-10	6 mi
Registration #2	2010-10-08	23.231 mi
Registration #3	2011-10-07	26.672 mi
Registration #4	2012-10-02	32.057 mi
Registration #5	2013-10-17	37.384 mi
Registration #6	2013-10-19	37.384 mi
Registration #7	2014-10-28	42.936 mi
Registration #8	2015-10-30	47.412 mi
Registration #9	2016-10-27	48.989 mi
Registration #10	2017-10-04	51.651 mi
Registration #11	2018-10-01	55.277 mi
Registration #12	2019-10-01	59.277 mi
Registration #13	2020-10-01	63.277 mi
Registration #14	2021-10-01	67.277 mi
Registration #15	2022-10-01	71.277 mi
Registration #16	2023-10-01	75.277 mi
Registration #17	2024-10-01	79.277 mi
Registration #18	2025-10-01	83.277 mi
Registration #19	2026-10-01	87.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1393 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BFS 062004