





report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE
Colour	Black
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2023-05-20

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-02-06	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-05-15
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	9
Total items failed	6

MOT #10	2023-05-16 15:22
MOT test number	992995958340
Result	✓ Passed
Next expiry date	2024-05-15

MOT #	9	2023-05-16 14:57
MOT te	st number	926451558072
Result		🗙 Failed
Fail	Nearside Front Road wheel fixing missing (5.2.1 (a) (i))	
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Front Road wheel fixing missing (5.2.1 (a) (i))	
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (i	ii))

MOT #8	2021-03-01 09:08
MOT test number	579152966835
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #7 2021-02-27 12:35

MOT test number 995485277833

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))

MOT #6 2019-06-17 13:32

MOT test number 987646503019

Result \rightarrow Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5 2018-06-21 09:30

MOT test number 746464918704

Result

Passed

Advice Wipers smearing

MOT #4 2017-06-15 15:50

MOT test number 365133499276

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2016-06-29 13:04

MOT test number 998162591387

Result ✓ Passed

CarCheck.co.uk page 4/12



Result

YA12GCU report date: 2024-03-29

X Failed

MOT #2 2015-04-17 16:08

MOT test number 766527605147

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2015-04-17 16:08

MOT test number 147927105156

Pass with rectification Nearside Headlamp aim too low (1.8)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	15 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when mistery	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	NE UK
Plate since	
Current registration	NK STE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-07-09
Last registration	2023-05-16
Complete history	See info



Registration #1	2012-07-09	26 mi
Registration #2	2015-04-17	53.810 mi
Registration #3	2016-06-29	66.996 mi
Registration #4	2017-06-15	76.390 mi
Registration #5	2018-06-21	81.995 mi
Registration #6	2019-06-17	88.143 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12,

Number of axles2Engine number2041867