





report date: 2024-03-29

General information

Make	BMW
Model	M5
Colour	Black
Year of manufacture	2006
Top speed	155 mph
Gearbox	7 speed Manual

Engine & fuel consumption

Power	500 BHP
Max. torque	520 Nm at 6.100 rpm
Engine capacity	4.999 сс
Cylinders	10
Fuel type	Petrol
Consumption city	12.4 mpg
Consumption extra urban	27.7 mpg
Consumption combined	19.1 mpg
CO2 emission	357 g/km
CO2 label	M



CarCheck.co.uk page 1/13



Internet history


Entry 1

Date 2021-08-31

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-03-19
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	19
Total items failed	4

MOT #18	2024-03-20 15:05
MOT test number	951905225763
Result	✓ Passed
Next expiry date	2025-03-19

MOT #17	2024-03-18 09:13
MOT test number	820135506723
Result	X Failed
Fail Nearside Front Side repeater not working (4.4.1 (a) (ii))	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #16		2023-03-20 16:55
MOT test	number	456282897317
Result		✓ Passed
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))		
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.)	11 (c))

CarCheck.co.uk page 3/13



MOT #15 2021-10-27 15:47

MOT test number 996792800004

Result ✓ Passed

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Rear diff oil leak

Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

MOT #14 2020-10-26 14:51

MOT test number 251671405153

Result ✓ Passed

MOT #13 2019-10-10 11:56

MOT test number 322820428599

Result \(\sqrt{Passed} \)

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides slightly corroded (1.1.14 (a) (ii))

Advice Vehicle Undertrays fitted obscuring view to underside

Advice Front Tyre slightly damaged/cracking or perishing Both sides perished/cracking, low tread and worn on edges. Close to limit. (5.2.3 (d) (ii))

MOT #12 2018-08-30 14:23

MOT test number 290555154899

Advice Vehicle Undertrays fitted obscuring view to underside

MOT #11 2018-02-12 12:24

MOT test number 162813525135

Result ✓ Passed

CarCheck.co.uk page 4/13



MK06BYJ

report date: 2024-03-29

MOT test number 666177725694

Result ✓ Passed

MOT #9 2015-09-18 12:42

MOT test number 742888637919

Result ✓ Passed

MOT #8 2014-07-28 16:57

MOT test number 585809004249

Result ✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #7 2014-01-23 09:44

MOT test number 105393524024

MOT #6 2013-08-07 10:51

MOT test number 228019713241

Result \(\sqrt{Passed} \)

Advice Inner Rear Brake pad(s) wearing thin (3.5.1g)

Advice Inner Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2012-08-07 12:16

MOT test number 575530922239

Result ✓ Passed

CarCheck.co.uk page 5/13



Fail

MK06BYJ report date: 2024-03-29

MOT #4 2011-08-09 12:15

MOT test number 538301521271

MOT #3 2010-02-24 14:53

MOT test number 101105250449

Result

Passed

MOT #2 2009-03-03 15:47

MOT test number 341792569046

Result
✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2009-03-02 12:23

MOT test number 590401269015

Result × Failed

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	19 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report here .	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-01
Last registration	2024-03-20
Complete history	See info



Registration #1	2006-03-01	6 mi
Registration #2	2009-03-02	17.374 mi
Registration #3	2009-03-03	17.414 mi
Registration #4	2010-02-24	23.633 mi
Registration #5	2011-08-09	30.528 mi
Registration #6	2012-08-07	35.611 mi
Registration #7	2013-08-07	42.468 mi
Registration #8	2014-01-23	43.526 mi
Registration #9	2014-07-28	47.219 mi
Registration #10	2015-09-18	52.738 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		91,700 esi
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

_ D:	mer	 -	ς,		~ 1	~+
			\sim	M = 1	М	

Width	1846 mm
Height	1469 mm
Length	4855 mm
Wheel base	2830 mm
Kerb weight	1830 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	60093718

CarCheck.co.uk page 13/13