



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	AMICA GSI
Colour	Blue
Year of manufacture	2006
Top speed	91 mph
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	97 Nm at 3.000 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-08-28
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-07-20
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	35
Total items failed	13

MOT #22	2023-07-21 07:58
MOT test number	350634173093
Result	✓ Passed
Next expiry date	2024-07-20
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21	2022-07-18 12:00
MOT test number	257328581982
Result	✓ Passed

MOT #20	2021-07-19 10:42
MOT test number	592895131139
Result	✓ Passed
Advice	Offside Front wheel stiff to rotate
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #19** 2020-06-17 10:13**MOT test number** 224764370674**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing OLD (5.2.3 (d) (ii))**Advice** Bonnet safety catch stiff**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #18** 2019-04-23 11:08**MOT test number** 687777050999**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**MOT #17** 2019-04-23 11:08**MOT test number** 859931479568**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**MOT #16** 2018-04-27 14:58**MOT test number** 391270480589**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)



MOT #15	2017-04-27 10:25
MOT test number	547184612275
Result	✓ Passed
Advice	Both front tyres wearing on inner edges

MOT #14	2017-04-27 10:25
MOT test number	579262612288
Result	✗ Failed
Pass with rectification	Offside Rear Lower Stop lamp not working (1.2.1b)
Advice	Both front tyres wearing on inner edges
Pass with rectification	Nearside Rear Upper Stop lamp not working (1.2.1b)
Pass with rectification	Nearside Front Headlamp not working on dipped beam (1.7.5a)

MOT #13	2016-04-22 10:42
MOT test number	650084976685
Result	✓ Passed
Advice	Offside Rear Upper brake bulb inop [done]
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)
Advice	Both rear tyres cracking up [age]

**MOT #12** 2016-04-22 10:42**MOT test number** 758900398746**Result** ✗ Failed**Advice** Offside Rear Upper brake bulb inop [done]**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Both rear tyres cracking up [age]**Pass with rectification** Bonnet retaining device ineffective (8.4.2)**MOT #11** 2015-04-30 11:32**MOT test number** 196750025173**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2015-04-30 11:32**MOT test number** 375500025155**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Headlamp not working on main beam (1.7.5a)**MOT #9** 2014-04-26 12:06**MOT test number** 379136414134**Result** ✓ Passed**Notice** Both rear tyres cracking up due to age

**MOT #8** 2014-04-26 12:06**MOT test number** 328766414139**Result** ✗ Failed**Pass with rectification** Offside Rear Lower Stop lamp not working (1.2.1b)**Notice** Both rear tyres cracking up due to age**Pass with rectification** Nearside Rear Upper Stop lamp not working (1.2.1b)**MOT #7** 2013-04-27 14:17**MOT test number** 915277113132**Result** ✓ Passed**Notice** N/s/f door mirror temp repaired.**MOT #6** 2012-04-28 10:36**MOT test number** 546589112113**Result** ✓ Passed**Notice** Bonnet safety catch stiff (have oiled).**MOT #5** 2012-04-28 10:36**MOT test number** 356599912179**Result** ✗ Failed**Notice** Bonnet safety catch stiff (have oiled).**Pass with rectification** Centre Front Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**MOT #4** 2011-04-27 11:54**MOT test number** 707507711140**Result** ✓ Passed**Notice** Bonnet safety catch starting to sieze.**Notice** N/s/r tyre has a cut in outer shoulder, but not exposing structure.

**MOT #3** 2010-04-27 12:59**MOT test number** 581997010110**Result** ✓ Passed**Notice** Bonnet safety catch siezed in open position (have freed it off)**MOT #2** 2010-04-27 12:59**MOT test number** 331897810165**Result** ✗ Failed**Pass with rectification** Outer Front Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Notice** Bonnet safety catch siezed in open position (have freed it off)**MOT #1** 2009-04-25 15:00**MOT test number** 143055019156**Result** ✓ Passed**Notice** Handbrake travel quite high.**Notice** Bonnet safety catch siezed in open position.**Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
20 July 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 CX06XXU
Plate since	2019-03-28
Current registration	 CX06XXU
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-04-28
Last registration	2023-07-21
Complete history	See info



Registration #1	2006-04-28	6 mi
Registration #2	2009-04-25	5.535 mi
Registration #3	2010-04-27	11.552 mi
Registration #4	2011-04-27	15.226 mi
Registration #5	2012-04-28	15.654 mi
Registration #6	2013-04-27	15.826 mi
Registration #7	2014-04-26	16.451 mi
Registration #8	2015-04-30	19.675 mi
Registration #9	2016-04-22	22.737 mi
Registration #10	2016-04-22	22.737 mi
Registration #11	2016-04-22	22.737 mi
Registration #12	2016-04-22	22.737 mi
Registration #13	2016-04-22	22.737 mi
Registration #14	2016-04-22	22.737 mi
Registration #15	2016-04-22	22.737 mi
Registration #16	2016-04-22	22.737 mi
Registration #17	2016-04-22	22.737 mi
Registration #18	2016-04-22	22.737 mi
Registration #19	2016-04-22	22.737 mi
Registration #20	2016-04-22	22.737 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1525 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	1007 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	G4HG6M912417