



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D2 R-DESIGN
Colour	Silver
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-09
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-11-28
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	14
Total items failed	13

**MOT #15** 2023-11-23 16:50**MOT test number** 969412874956**Result** ✓ Passed**Next expiry date** 2024-11-28

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #14** 2023-11-22 12:06**MOT test number** 497797780028**Result** ✗ Failed

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))

**Fail** Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #13** 2022-11-29 12:34**MOT test number** 242710947598**Result** ✓ Passed

**MOT #12** 2022-11-28 12:58**MOT test number** 880268536994**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2021-11-16 15:27**MOT test number** 517947333826**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2021-11-03 10:51**MOT test number** 675756688491**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #9** 2020-09-14 13:01**MOT test number** 165102227974**Result** ✓ Passed**MOT #8** 2019-04-06 10:32**MOT test number** 121968057892**Result** ✓ Passed**MOT #7** 2018-04-11 07:47**MOT test number** 720385259515**Result** ✓ Passed

**MOT #6** 2018-04-09 10:27**MOT test number** 769944109791**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #5** 2017-03-31 15:43**MOT test number** 169673235730**Result** ✓ Passed**MOT #4** 2017-03-29 10:52**MOT test number** 702884761159**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #3** 2016-04-01 15:17**MOT test number** 383764144200**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Upper Rear position lamp(s) has light sources not illuminating, but not more than 50% sidelight failed on test (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2015-03-26 13:58
MOT test number	315045385077
Result	✓ Passed
Notice	O/s/f inner cv boot begining to leak grease

MOT #1	2014-03-14 17:25
MOT test number	537843274085
Result	✓ Passed
Notice	Wipers deteriorated
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
28 November 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	28 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>BF11SJX</b>
Plate since	2019-09-28
Current registration	<b>BF11SJX</b>
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-14
Last registration	2023-11-23
Complete history	<a href="#">See info</a>



Registration #1	2011-03-14	19 mi
Registration #2	2014-03-14	44.354 mi
Registration #3	2015-03-26	55.776 mi
Registration #4	2016-04-01	83.062 mi
Registration #5	2017-03-29	71.600 mi
Registration #6	2017-03-31	71.600 mi
Registration #7	2018-04-09	79.459 mi
Registration #8	2018-04-11	79.459 mi
Registration #9	2019-04-06	95.202 mi
Registration #10	2020-03-29	95,202 miles
Registration #11	2020-03-29	95,202 miles
Registration #12	2020-03-29	95,202 miles
Registration #13	2020-03-29	95,202 miles
Registration #14	2020-03-29	95,202 miles
Registration #15	2020-03-29	95,202 miles
Registration #16	2020-03-29	95,202 miles
Registration #17	2020-03-29	95,202 miles

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1708102