



report date: 2024-03-28

General information

Make	VOLVO
Model	S80 D5 SE LUX
Colour	Bronze
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	169 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-02-28
Pictures	12
Listing price	View report



source: yesauto.com

**MOT history**

MOT expiry date	2025-03-15
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	31
Total items failed	3

MOT #17 2024-03-14 19:57**MOT test number** 910716462446**Result** ✓ Passed**Next expiry date** 2025-03-15

- Minor** Horn control insecure (7.7 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #16 2024-03-14 19:57**MOT test number** 142790107788**Result** ✗ Failed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Horn control insecure (7.7 (b))
- Pass with rectification** Horn sound not in accordance with requirements (7.7 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #15** 2023-03-16 18:10**MOT test number** 457408312527**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2021-09-16 16:21**MOT test number** 394204000428**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2020-06-09 10:01**MOT test number** 960152184842**Result** ✓ Passed**MOT #12** 2019-05-11 10:16**MOT test number** 763263665910**Result** ✓ Passed**Advice** Offside Front Play in steering rack inner joint(s)**Advice** One of rear exhaust brackets snapped**Advice** Corrosion to parts of exhaust

**MOT #11** 2018-05-26 10:48**MOT test number** 753001672780**Result** ✓ Passed**Advice** Offside Rear Suspension component pin or bush slightly worn Trailing arm bush (5.3.4 (a) (i))**Advice** Offside Play in steering rack inner joint(s)**Advice** Nearside Rear Suspension component pin or bush slightly worn Trailing arm bush (5.3.4 (a) (i))**MOT #10** 2017-05-31 08:51**MOT test number** 202530522544**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9** 2016-06-18 10:05**MOT test number** 264303484534**Result** ✓ Passed**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #8** 2015-06-22 12:47**MOT test number** 747733275122**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Rear tyres stepped**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #7** 2014-07-05 11:20**MOT test number** 776076784136**Result** ✓ Passed**MOT #6** 2013-06-15 12:05**MOT test number** 257376963147**Result** ✓ Passed**MOT #5** 2013-06-15 10:08**MOT test number** 278156263475**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #4** 2012-06-11 17:31**MOT test number** 297693662413**Result** ✓ Passed**MOT #3** 2012-06-11 17:31**MOT test number** 568743362161**Result** ✗ Failed**Pass with rectification** Offside Side repeater not working (1.4.A.2c)**MOT #2** 2011-12-09 09:34**MOT test number** 875803741375**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2010-12-14 12:41
MOT test number	424668140351
Result	✓ Passed
Notice	Engine oil level low.
Advice	Offside Side repeater slightly discoloured (1.4.A.2f)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
15 March 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AJ57XKH
Plate since	2019-09-28
Current registration	AJ57XKH
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-11-29
Last registration	2024-03-14
Complete history	See info



Registration #1	2007-11-29	18 mi
Registration #2	2010-12-14	30.609 mi
Registration #3	2011-12-09	38.576 mi
Registration #4	2012-06-11	41.068 mi
Registration #5	2013-06-15	51.806 mi
Registration #6	2013-06-15	51.808 mi
Registration #7	2014-07-05	59.607 mi
Registration #8	2015-06-22	66.515 mi
Registration #9	2016-06-18	77.578 mi
Registration #10	2016-06-18	77.578 mi
Registration #11	2016-06-18	77.578 mi
Registration #12	2016-06-18	77.578 mi
Registration #13	2016-06-18	77.578 mi
Registration #14	2016-06-18	77.578 mi
Registration #15	2016-06-18	77.578 mi
Registration #16	2016-06-18	77.578 mi
Registration #17	2016-06-18	77.578 mi
Registration #18	2016-06-18	77.578 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1570 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number

490903