





report date: 2024-03-28

## General information

Make	VAUXHALL
Model	CROSSLAND
Colour	Blue
Year of manufacture	2018
Top speed	117 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	128 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.199 сс
Cylinders	3
Fuel type	Petrol
Consumption combined	44.1 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 6

Date 2022-04-04

Pictures 1

Listing price <u>View report</u>



#### source: autoonline.co.uk

#### Entry 5

Date 2022-01-18

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

### Entry 4

Date 2021-12-16

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

#### Entry 3

Date 2021-12-03
-----------------

CarCheck.co.uk page 2/11

Pictures	0

Listing price	View report	

## source: heycar.co.uk


## Entry 2

Date	2021-12-01
------	------------

Pictures 16

Listing price <u>View report</u>









#### source: autotrader.co.uk

## Entry 1

Date	2021-11-30
Pictures	0
Listing price	View report

source: heycar.co.uk



report date: 2024-03-28

# MOT history

MOT expiry date	2024-06-30
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	5
Total items failed	2

MOT #4		2023-07-01 14:17
MOT test	number	585468120157
Result		✓ Passed
Next expiry date 2024-06-3		2024-06-30
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #3	2023-07-01 13:14
MOT test number	125998028334
Result	<b>X</b> Failed
Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
<b>Fail</b> Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously wea	akened (1.1.14 (a) (ii))

MOT #2	2022-05-04 17:05
MOT test number	835817009148
Result	✓ Passed
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14)	4 (a) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2021-08-26 11:05

**MOT test number** 125836996685

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	30 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

**Type** 

Damage 2

**Date** 

Category

Type



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlondere.	
***************************************	
Plate changes	More info >
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2018-09-20
Last registration	2023-07-01
Complete history	See info



Registration #1	2018-09-20	14 mi
Registration #2	2021-08-26	18.186 mi
Registration #3		11.777 esi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

# Safety ratings

NCAP rating	****
Adult	84%
Children	87%
Pedestrian	63%
Safety systems	60%
Overall rating	76%
Video	see crash video



# Dimensions & weight

Width	1856 mm
Height	1609 mm
Length	4477 mm
Wheel base	2675 mm
Kerb weight	1350 kg
Max. allowed weight	1910 kg

# Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	10XTA11015104 LES

CarCheck.co.uk page 11/11