



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI BLUEMOTION TECHNOLOGY
Colour	Blue
Year of manufacture	2018
Top speed	123 mph
0 - 100 km/h	10.2 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	85 kW / 116 HP / 113 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	106 g/km
CO2 label	B





Internet history

Entry 2

Date	2021-07-23
Pictures	3
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-23
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-06
MOT pass rate	100 %
MOT passed	3
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #3	2023-07-01 10:56
MOT test number	824476513307
Result	✓ Passed
Next expiry date	2024-07-06
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2	2022-07-07 14:21
MOT test number	297144320675
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))



MOT #1 2021-03-05 11:05

MOT test number 862101933786

Result ✓ Passed

- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Both front shockers light misting of oil
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
6 July 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BN180AU
Plate since	2019-03-29
Current registration	 BN180AU
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-03-12
Last registration	2023-07-01
Complete history	See info



Registration #1	2018-03-12	25 mi
Registration #2	2021-03-05	35.629 mi
Registration #3	2022-03-05	35.629 mi
Registration #4	2022-03-05	35.629 mi
Registration #5	2022-03-05	35.629 mi
Registration #6	2023-07-01	35.629 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	89%
Pedestrian	65%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2027 mm
Height	1492 mm
Length	4258 mm
Wheel base	2620 mm
Kerb weight	1223 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2

Engine number

DDYA635499