



General information

Make	FORD
Model	FOCUS ZETEC TDCI
Colour	Black
Year of manufacture	-
Top speed	117 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	260 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-20
Pictures	25
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #16	2022-09-21 13:45
MOT test number	108566392228
Result	✓ Passed
Next expiry date	2023-09-28
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2022-09-21 09:35
MOT test number	772336342450
Result	✗ Failed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Offside Rear Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Service brake excessively binding (1.2.1 (f))

MOT #14	2021-09-15 11:26
MOT test number	818583154504
Result	✓ Passed

MOT #13	2021-09-14 10:26
MOT test number	312348413351
Result	✗ Failed
Fail	Nearside Rear Anti-roll bar linkage pin or bush excessively worn broken (5.3.4 (a) (i))
Fail	Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Fail	Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**MOT #12** 2020-09-29 10:51**MOT test number** 374300481499**Result** ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Perished on both edges (5.2.3 (d) (ii))

MOT #11 2019-07-01 13:45**MOT test number** 648551941223**Result** ✓ Passed**MOT #10** 2019-06-29 10:59**MOT test number** 250679374344**Result** ✗ Failed

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #9 2018-06-28 09:36**MOT test number** 793696284741**Result** ✓ Passed**MOT #8** 2017-07-04 09:15**MOT test number** 507506302084**Result** ✓ Passed

**MOT #7** 2017-07-03 11:30**MOT test number** 271130379544**Result** ✗ Failed

- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)

MOT #6 2016-06-01 14:24**MOT test number** 615933062229**Result** ✓ Passed

- Advice** Child seats fitted

MOT #5 2016-05-31 09:10**MOT test number** 421735161697**Result** ✗ Failed

- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Child seats fitted
- Fail** Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #4 2015-05-13 16:13**MOT test number** 979553835174**Result** ✓ Passed

**MOT #3** 2015-05-12 12:12**MOT test number** 508632035165**Result** ✗ Failed**Fail** Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front tyres worn on inner edges**Fail** Offside Registration plate lamp not illuminating the registration plate (1.1.C.1e)**Fail** Brakes imbalanced across an axle (3.7.D.2c)**MOT #2** 2014-06-06 14:47**MOT test number** 255967254458**Result** ✓ Passed**MOT #1** 2013-05-01 11:07**MOT test number** 276811723465**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-31
Last registration	2022-09-21
Complete history	See info



Registration #1	2010-03-31	20 mi
Registration #2	2013-05-01	38.801 mi
Registration #3	2014-06-06	52.151 mi
Registration #4	2015-05-12	69.456 mi
Registration #5	2015-05-13	69.450 mi
Registration #6	2016-05-31	88.838 mi
Registration #7	2016-06-01	88.838 mi
Registration #8	2017-07-03	109.364 mi
Registration #9	2017-07-04	109.364 mi
Registration #10	2017-07-04	109.364 mi
Registration #11	2017-07-04	109.364 mi
Registration #12	2017-07-04	109.364 mi
Registration #13	2017-07-04	109.364 mi
Registration #14	2017-07-04	109.364 mi
Registration #15	2017-07-04	109.364 mi
Registration #16	2017-07-04	109.364 mi
Registration #17	2017-07-04	109.364 mi
Registration #18	2017-07-04	109.364 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2020 mm
Height	1503 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1391 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AY47242