





General information

Make	MERCEDES
Model	CLK CLK200K AVANTGARDE
Colour	Black
Year of manufacture	2005
Top speed	142 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 4.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	207 g/km
CO2 label	К







Internet history

Entry 1

Date Pictures 2021-07-14

11

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-12-13
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	16
Total items failed	15

MOT #19		2022-12-14 10:50
MOT test n	umber	289350725120
Result		✓ Passed
Next expiry date 2023-12-1		2023-12-13
Minor R	Registration plate lamp inoperative in the case of multiple lamps or light	sources (4.7.1 (b) (i))
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))	

MOT #18		2021-11-05 18:13
MOT test	number	808910826086
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))	
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))	
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light so	ources (4.7.1 (b) (i))



SA55XHT
report date: 2024-03-28

MOT #17		2020-10-23 13:27
MOT test	number	882736317690
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #16		2018-03-29 07:56

MOT test number	154648134578
Result	✓ Passed

MOT #2	15	2018-03-26 08:40
MOT te	st number	418897769258
Result		🗙 Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Nearside Front Tyre(s) incorrect because a lightweight or space saving wheel is	fitted (4.1.A.1b)
Fail	Registration plate lamp not working (1.1.C.1d)	
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)	

MOT #14	2017-03-13 17:39
MOT test number	229785081381
Result	✓ Passed

MOT #13	2016-03-16 16:30
MOT test number	555102015844
Result	✓ Passed



SA55XHT
report date: 2024-03-28

MOT #3	12	2016-03-16 12:54
MOT te	st number	591225408558
Result		🗙 Failed
Fail	Offside Front coil spring broken (2.4.C.1a)	
MOT #3	11	2015-03-14 17:31
MOT te	st number	585723975027
Result		✓ Passed
MOT #3	10	2014-08-08 10:13
MOT te	st number	958650924297
Result		✓ Passed
MOT #9		2014-08-07 13:03
Result	st number	379629714402
Result		× raileu
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail	Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)	
Fail	Rear parking brake recording little or no effort (3.7.B.6a)	
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)	
Fail	Offside Track rod end ball joint has excessive play (2.2.B.1f)	
Fail	Offside Rear Direction indicator incorrect colour (1.4.A.2f)	

MOT #8	2013-07-23 16:15
MOT test number	975234803238
Result	✓ Passed





MOT #7	2012-12-11 15:03
MOT test number	135696442341
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice ADVISE FRONT BRAKE DISCS SCORED	
Notice ADVISE DAMAGE TO NSR TYRE SIDEWALL	

MOT #6	2012-12-10 12:01
MOT test number	717315542382
Result	× Failed
Notice ADVISE FRONT BRAKE DISCS SCORED	
Advice Offside Rear Tyre worn close to the lea	gal limit (4.1.E.1)
Notice ADVISE DAMAGE TO NSR TYRE SIDEW	ALL
Fail Nearside Front coil spring fractured (2.4.0)	C.1a)

MOT #5	2011-10-19 09:11
MOT test number	198712691242
Result	✓ Passed
Notice Advise o/s/f tyre worn on outer edge.	
MOT #4	2010-12-21 10:04
MOT test number	491885050420
Result	✓ Passed
MOT #3	2009-09-15 15:27

2009-09-15 15:27
973278959285
✓ Passed





MOT #2	2009-09-11 12:39
MOT test number	894124959221
Result	🗙 Failed
Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	
MOT #1	2008-09-20 10:34
MOT test number	112934168250
Result	✓ Passed





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	AAMP
Туре	
Damage 2	AMPL
Date	4
Category	ANDEL
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-09-29
Last registration	2022-12-14
Complete history	See info



Registration #1	2005-09-29	21 mi
Registration #2	2008-09-20	23.546 mi
Registration #3	2009-09-11	30.956 mi
Registration #4	2009-09-15	30.956 mi
Registration #5	2010-12-21	34.537 mi
Registration #6	2011-10-19	37.190 mi
Registration #7	2012-12-10	40.234 mi
Registration #8	2012-12-11	40.234 mi
Registration #9	2013-07-23	41.728 mi
Registration #10	2014-08-07	58.717 mi
Registration #11	2014-08-08	58.717 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.777 mi
Registration #21		

More info >





Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1615 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27194030678660