





report date: 2024-03-29

General information

Make	KIA
Model	RIO 3 ISG
Colour	Black
Year of manufacture	2016
Top speed	114 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	137 Nm at 4.200 rpm
Engine capacity	1.396 сс
Cylinders	4
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-07-30


Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT r	nistory
-------	---------

MOT expiry date	2025-04-16
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	23
Total items failed	0

	2024-04-09 17:21
number	764399851130
	✓ Passed
ry date	2025-04-16
Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.13	L (c))
Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
TPMS Light On	
	y date Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.13) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7	2023-04-17 15:06
MOT test number	448918382809
Result	✓ Passed

CarCheck.co.uk page 3/12



Result

ST66WJC report date: 2024-03-29

✓ Passed

MOT #6 2022-08-23 16:14

MOT test number 943588941157

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear wiper torn

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #5 2022-08-18 14:54

MOT test number 804527820622

Result × Failed

Advice Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Nearside Rear Service brake excessively fluctuating (1.2.1 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Rear wiper blade rubber split

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Offside Rear Tyre(s) with different aspect ratios are fitted on the same axle. wrong size of tyre fitted to offside rear (5.2.3 (b))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



MOT #4 2021-08-03 15:55

MOT test number 893392021874

MOT #3 2021-08-03 06:53

MOT test number 344608456725

Result X Failed

Advice Tpms light on dash

Advice Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))

MAJOR Windscreen washer provides insufficient washer liquid both front (3.5 (a))

MOT #2 2020-08-01 11:07

MOT test number 409953130697

Result ✓ Passed

MOT #1 2019-08-21 11:16

MOT test number 387755374881

Result \rightarrow Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



ST66WJC

report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

faste since

ST66WJC

report date: 2024-03-29

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

See in this check if this KIA had different number plates.

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-12-15
Last registration	2024-04-09
Complete history	See info



Registration #1	2016-12-15	21 mi
Registration #2	2019-08-21	27.308 mi
Registration #3	2020-08-01	32.556 mi
Registration #4		11.777 es
Registration #5	2021-08-03	38.161 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.00 m
		11.77 m
Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4050 mm
Wheel base	2570 mm
Kerb weight	1227 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	43 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number G4FAGS023199