





report date: 2024-03-28

General information

Make	RENAULT
Model	MODUS GRAND DYNAMIQUE VVT
Colour	Silver
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	82 kW / 112 HP / 110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	179 g/km
CO2 label	I



CarCheck.co.uk page 1/12



LR11ZMO

report date: 2024-03-28

Internet history

Entry 1

Date	2021-07-10	
Pictures	2	
Listing price	View report	





source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-08
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	16
Total items failed	5

MOT #14		2023-07-04 14:33
MOT test	number	326683171092
Result		✓ Passed
Next expi	ry date	2024-07-08
Advice	Front Macpherson strut corroded but not seriously weakened both sides (5	5.3.3 (b) (i))
Minor	Nearside Obligatory mirror slightly loose (3.3 (b) (i))	
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps of	or light sources (4.7.1

MOT #13		2022-07-01 07:35
MOT test	number	286671628817
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	())
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2021-07-09 14:52
MOT test	number 321389149512
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



LR11ZMO

report date: 2024-03-28

MOT #11 2021-06-07 10:22

MOT test number 282611302045

Result X Failed

Fail
Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #10 2020-07-03 13:15

MOT test number 244299694887

Result Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2020-07-03 07:51

MOT test number 608971039764

Result X Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2019-06-03 08:25

MOT test number 662707377629

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2018-06-01 09:38

MOT test number 514377695151

Result

Passed

CarCheck.co.uk page 4/12



MOT #6 2018-06-01 08:23

MOT test number 171054743310

Result X Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))

MOT #5 2017-06-02 11:14

MOT test number 839914707981

Result \(\sqrt{Passed} \)

MOT #4 2017-06-02 08:18

MOT test number 368990381942

Result X Failed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Nearside rear brake binding (3.7.B.1)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #3 2016-06-21 14:16

MOT test number 618726397537

Result \rightarrow Passed

MOT #2 2015-06-24 09:05

MOT test number 248615975100

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2014-06-25 09:08

MOT test number 536156774109

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	8 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NK NAME OF THE PARTY OF THE PAR
Plate since	
Current registration	NK NK
Plate since	
	More info

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-24
Last registration	2023-07-04
Complete history	See info



Registration #1	2011-03-24	18 mi
Registration #2	2014-06-25	29.719 mi
Registration #3	2015-06-24	41.661 mi
Registration #4	2016-06-21	52.783 mi
Registration #5	2017-06-02	60.677 mi
Registration #6	2017-06-02	60.683 mi
Registration #7	2018-06-01	68.614 mi
Registration #8	2018-06-01	68.614 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1967 mm
Height	1586 mm
Length	4034 mm
Wheel base	2482 mm
Kerb weight	1235 kg
Max. allowed weight	1722 kg

Additional information

Fuel tank capacity	51	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	e 12/12

Number of axles2Engine numberD042160