





General information

Make	LAND ROVER
Model	DISCOVERY SPORT TD4 LANDMARK
Colour	Black
Year of manufacture	2019
Top speed	117 mph
0 - 60 mph	8.9 seconds
Gearbox	9 speed automatic


Engine & fuel consumption

Power	178 BHP
Max. torque	430 Nm at 1.750 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	42.8 mpg
CO2 emission	170 g/km
CO2 label	Н



RK19EVW report date: 2024-03-29

Internet history





MOT history

MOT expiry date	2024-05-08
MOT pass rate	50 %
MOT passed	2
Failed MOT tests	2
Total advice items	11
Total items failed	3

МОТ #4	2023-05-09 15:47
MOT test number	773309625767
Result	✓ Passed
Next expiry date	2024-05-08
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) ((ii))

МОТ #3	2023-05-02 11:55
MOT test number	539308847276
Result	🗙 Failed
Fail Offside Front Lower Windscreen damaged and affecting the driver's view of th	e road (3.2 (a) (ii))
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	





МОТ #2	2022-03-28 09:59
MOT test number	993989386208
Result	✓ Passed
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weak (1.1.14 (a) (ii))	kened rust rings forming
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weake (1.1.14 (a) (ii))	ned rust rings forming

MOT #1	2022-03-26 10:41
MOT test number	494691783478
Result	🗙 Failed
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weat (1.1.14 (a) (ii))	akened rust rings forming
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough cut to cords (5.2.3 (d) (i))	to reach the ply or cords 2 x
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weak (1.1.14 (a) (ii))	ened rust rings forming
Fail Rear Registration plate does not conform to the specified requirements plate	late delaminated (0.1 (d))





Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
	MP1E
Category	ter .
Туре	

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





.....

Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE	

And a second sec	

	More info >
Plate changes	

Number of plates

Current registration

Plata since

More info >





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-04-23
Last registration	2023-05-09
Complete history	See info



Registration #1	2019-04-23	19 mi
Registration #2	2022-03-26	30.115 mi
Registration #3	2022-03-28	30.234 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		10.000 est

More info \rightarrow





Safety ratings

NCAP rating	****
Adult	93%
Children	83%
Pedestrian	69%
Safety systems	82%
Overall rating	84%
Video	see crash video



Dimensions & weight	
Width	2173 mm
Height	1724 mm
Length	4599 mm
Wheel base	2741 mm
Max. allowed weight	2660 kg
Additional information	
Additional information Fuel tank capacity	54 I
	54 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5