





report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2014
Top speed	102 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-29

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



WM63NND report date: 2024-03-28

2023-09-07 10:29

MOT history

MOT #13

MOT expiry date	2024-10-03
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	9
Total items failed	8

MOT #14	2023-09-07 12:19
MOT test number	275480077350
Result	✓ Passed
Next expiry date	2024-10-03

MOT test	t number 445501236305
Result	▼ Failed
MAIOD	Negraide Front Anti-roll har linkage hall joint dust sover no langue provents the ingress of dist

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #12		2022-09-30 16:07
MOT test	number	261340101370
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge worn on inner e	edge (5.2.3 (e))

MOT #11	2022-09-14 09:4	17
MOT test	number 15301462453	32
Result	★ Faile	ed.
MAJOR	Offside Rear Brake hose excessively chafed hose has been rubbing on exhaust shield (1.1.12 (b)	
Advice	Offside Rear tyre is worn on inner edge	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10 2021-10-04 11:47

MOT test number 478428788619

MOT #9 2021-10-04 11:47

MOT test number 387180848553

Result X Failed

Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))

Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))

MOT #8 2020-11-05 16:04

MOT test number 316955213803

Result \rightarrow Passed

MOT #7 2020-11-05 13:20

MOT test number 802436178043

Result X Failed

Advice Nearside Front Nail in tyre

Advice The rear exhaust silencer badly damaged.

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Nearside Rear reflector missing (4.8.2 (a) (ii))

MAJOR Nearside Rear Shock absorbers insecurely attached (5.3.2 (a) (i))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

MAJOR Offside Rear reflector missing (4.8.2 (a) (ii))

Pass with rectification Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no

longer prevents the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6	2019-10-16 14:25

MOT test number 933940399292

MOT #5 2018-10-10 08:42

MOT test number 107755004438

Result

Passed

MOT #4 2017-11-02 11:04

MOT test number 523745595577

Result
✓ Passed

MOT #3 2017-11-01 12:23

MOT test number 810932004535

Result × Failed

Fail Power steering pipe(s) or hose(s) leaking return pipe (2.3.3b)

MOT #2 2016-11-10 08:30

MOT test number 472542637015

MOT #1 2016-11-10 08:30

MOT test number 962630214397

Result X Failed

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

Pass with rectification Offside Headlamp aim too low (1.8)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	3 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

O	والمراجع والأجا
Owner	nistorv

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{k}}$	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK WIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-01-28
Last registration	2023-09-07
Complete history	See info



Registration #1	2014-01-28	22 mi
Registration #2	2016-11-10	21.382 mi
Registration #3	2016-11-10	21.382 mi
Registration #4	2017-11-01	25.940 mi
Registration #5	2017-11-02	25.943 mi
Registration #6	2018-10-10	42.141 mi
Registration #7	2019-10-16	58.362 mi
Registration #8	2020-11-05	72.030 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91,700 esi

PRIN. 20. 20

More info >

77,777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air condition
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1445 kg
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number CarCheck.co.uk	7097830 page 12/12