



**BK60BOV**

report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V SX MULTIJET
Colour	Blue
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	5.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-17
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-15
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	20
Total items failed	1

MOT #14	2023-09-14 12:58
MOT test number	448548203295
Result	✓ Passed
Next expiry date	2024-09-15

MOT #13	2022-09-16 14:20
MOT test number	410166145521
Result	✓ Passed
Minor	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #12	2022-09-16 13:38
MOT test number	149861754746
Result	✗ Failed
Minor	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
DANGEROUS	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #11** 2021-10-22 05:18**MOT test number** 820600288017**Result** ✓ Passed**Advice** Clutch pedal anti slip missing**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #10** 2021-07-28 08:23**MOT test number** 726953923422**Result** ✓ Passed**Minor** Front Windscreen damaged but not adversely affecting driver's view chips (3.2 (a) (i))**MOT #9** 2020-08-18 07:45**MOT test number** 871271953290**Result** ✓ Passed**MOT #8** 2019-08-07 08:32**MOT test number** 187780980141**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush BUSH (5.3.2 (c))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #7** 2018-08-10 12:28**MOT test number** 197408197099**Result** ✓ Passed**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #6** 2017-08-14 09:40**MOT test number** 964774301128**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Clutch pedal rubber missing.**Advice** Nearside Rear Tyre perishing/cracking.**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Front Tyre perishing/cracking.**MOT #5** 2016-08-06 08:31**MOT test number** 725246962588**Result** ✓ Passed**MOT #4** 2015-09-21 12:47**MOT test number** 240892806324**Result** ✓ Passed**Advice** Engine management warning lamp illuminated**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2015-09-01 14:15**MOT test number** 225692377193**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside rear tyre cracking**MOT #2** 2014-09-15 11:41**MOT test number** 606538454272**Result** ✓ Passed



MOT #1	2013-09-02 14:32
MOT test number	388795843209
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
15 September 2024


Tax status		Valid until 1 March
Days left		305
MOT expiry date		15 September 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-29
Last registration	2023-09-14
Complete history	<a href="#">See info</a>



Registration #1	2010-09-29	6 mi
Registration #2	2013-09-02	7.445 mi
Registration #3	2014-09-15	11.206 mi
Registration #4	2015-09-01	14.179 mi
Registration #5	2015-09-21	14.205 mi
Registration #6	2016-08-06	15.118 mi
Registration #7	2017-08-14	16.862 mi
Registration #8	2018-08-10	27.060 mi
Registration #9	2019-08-09	35.377 mi
Registration #10	2020-08-09	35.377 mi
Registration #11	2021-08-09	35.377 mi
Registration #12	2022-08-09	35.377 mi
Registration #13	2023-08-09	35.377 mi
Registration #14	2024-08-09	35.377 mi
Registration #15	2025-08-09	35.377 mi
Registration #16	2026-08-09	35.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1345 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	3645696