



H439WGN

report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 BASE
Colour	Silver
Year of manufacture	1991
Top speed	109 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	135 Nm at 4.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Petrol





Internet history

Entry 1

Date	2021-02-01
Pictures	3
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2022-01-18
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	26
Total items failed	8

MOT #16	2021-01-19 12:46
MOT test number	909151721267
Result	✓ Passed
Next expiry date	2022-01-18

MOT #15	2021-01-18 09:38
MOT test number	109589621748
Result	✗ Failed
MAJOR	Front Windscreen wiper does not clear the windscreen effectively Both sides (3.4 (b) (ii))
MAJOR	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #14	2019-07-13 11:04
MOT test number	196229769562
Result	✓ Passed

MOT #13	2015-05-14 10:56
MOT test number	506644335127
Result	✓ Passed

**MOT #12** 2014-05-20 10:52**MOT test number** 237130244158**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Front and rear suspension components corroded, but not to excess.**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #11** 2013-05-21 11:22**MOT test number** 766811243138**Result** ✓ Passed**MOT #10** 2012-05-01 13:02**MOT test number** 755432122184**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #9** 2011-05-06 11:21**MOT test number** 258036721163**Result** ✓ Passed**Notice** Both main fuel pipes heavily corroded.

**MOT #8** 2011-04-27 15:38**MOT test number** 825837211117**Result** ✗ Failed**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**Notice** Both main fuel pipes heavily corroded.**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #7** 2010-05-18 16:56**MOT test number** 352248230144**Result** ✓ Passed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #6** 2010-05-18 10:29**MOT test number** 251998130130**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content excessive (7.3.B.1a)**Advice** Offside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Front Brake pipe excessively corroded (3.6.B.2c)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)

**MOT #5**

2009-05-15 16:30

MOT test number

731615239195

Result

✓ Passed

- Notice** Front pads getting down
- Notice** Rear pads getting down
- Notice** O/s/f +both rears road springs corroded
- Notice** Under trays fitted
- Notice** Both front flexis starting to perish
- Notice** Rear axle +anti roll bar bushes all perished

MOT #4

2009-05-15 10:27

MOT test number

934675539159

Result

✗ Failed

- Fail** Nearside Front coil spring fractured (2.4.C.1a)
- Notice** Front pads getting down
- Notice** Clutch slave cinder weaping
- Notice** Both front flexis starting to perish
- Notice** Oil leak
- Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)
- Notice** Heat shelds loose
- Notice** All road springs corroded
- Notice** Rear pads getting down
- Notice** Under trays fitted



MOT #3	2008-05-16 11:11
MOT test number	461787838165
Result	✓ Passed
<div>NoticeSlight corrosion on outer seals at rear</div>	

MOT #2	2007-05-15 11:34
MOT test number	650295337152
Result	✓ Passed

MOT #1	2006-05-18 11:45
MOT test number	150248036124
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
17 July 2020

✕
MOT

Expired:
18 January 2022

Tax status	Expired at 17 July 2020
Days left	1381 days too late
MOT expiry date	18 January 2022
Full MOT history	See MOT history



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	1991-02-11
Last registration	2021-01-19
Complete history	See info



Registration #1	1991-02-11	19 mi
Registration #2	2006-05-18	100.028 mi
Registration #3	2007-05-15	100.609 mi
Registration #4	2008-05-16	101.416 mi
Registration #5	2009-05-15	102.109 mi
Registration #6	2009-05-15	102.109 mi
Registration #7	2010-05-18	102.786 mi
Registration #8	2010-05-18	102.786 mi
Registration #9	2011-04-27	103.449 mi
Registration #10	2012-05-15	103.449 mi
Registration #11	2013-05-15	103.449 mi
Registration #12	2014-05-15	103.449 mi
Registration #13	2015-05-15	103.449 mi
Registration #14	2016-05-15	103.449 mi
Registration #15	2017-05-15	103.449 mi
Registration #16	2018-05-15	103.449 mi
Registration #17	2019-05-15	103.449 mi
Registration #18	2020-05-15	103.449 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1675 mm
Height	1230 mm
Length	3970 mm

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	B6741852