



report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER TD COUNTY STATION WAGON
Colour	Blue
Year of manufacture	2010
Top speed	82 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel
Consumption city	22.6 mpg
Consumption extra urban	32.9 mpg
Consumption combined	28.3 mpg





Internet history

Entry 1

Date	2021-11-03
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-12-19
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	17
Total items failed	5

MOT #13	2022-12-07 08:21
MOT test number	943056646757
Result	✓ Passed
Next expiry date	2023-12-19

MOT #12	2021-11-30 10:12
MOT test number	566148744526
Result	✓ Passed

MOT #11	2021-11-29 13:26
MOT test number	450362872243
Result	✗ Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #10	2020-11-20 12:33
MOT test number	979576865134
Result	✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #9** 2020-11-18 16:30**MOT test number** 176025097524**Result** ✗ Failed**Fail** Fuel system component leaking (6.1.3 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #8** 2019-12-17 08:58**MOT test number** 286333995750**Result** ✓ Passed**MOT #7** 2018-12-20 10:51**MOT test number** 613813112734**Result** ✓ Passed**Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #6** 2017-11-10 10:13**MOT test number** 448143882608**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit is down to 1.6 mm in places (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Central Front Oil leak

**MOT #5** 2017-11-10 10:13**MOT test number** 396453033514**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Central Rear Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit is down to 1.6 mm in places (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Central Front Oil leak**MOT #4** 2016-10-06 10:23**MOT test number** 994057978659**Result** ✓ Passed**MOT #3** 2015-10-22 12:22**MOT test number** 894827883003**Result** ✓ Passed**MOT #2** 2014-11-06 10:56**MOT test number** 797580114365**Result** ✓ Passed**MOT #1** 2013-10-10 13:01**MOT test number** 745383183244**Result** ✓ Passed



Tax & MOT check

✓

Taxed

Tax due:
1 December 2024

✗

MOT

Expired:
19 December 2023

Tax status	Valid until 1 December
Days left	216
MOT expiry date	19 December 2023
Full MOT history	See MOT history



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	KY60UPP
Plate since	2024-03-28
Current registration	KY60UPP
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-10-31
Last registration	2022-12-07
Complete history	See info



Registration #1	2010-10-31	19 mi
Registration #2	2013-10-10	16.953 mi
Registration #3	2014-11-06	26.202 mi
Registration #4	2015-10-22	34.386 mi
Registration #5	2016-10-06	42.861 mi
Registration #6	2017-11-10	51.751 mi
Registration #7	2017-11-10	51.751 mi
Registration #8	2018-12-20	53.711 mi
Registration #9	2019-05-20	55.377 mi
Registration #10	2019-05-20	55.377 mi
Registration #11	2019-05-20	55.377 mi
Registration #12	2019-05-20	55.377 mi
Registration #13	2019-05-20	55.377 mi
Registration #14	2019-05-20	55.377 mi
Registration #15	2019-05-20	55.377 mi

More info >



Dimensions & weight

Width	1790 mm
Height	2128 mm
Length	3880 mm
Wheel base	2360 mm
Kerb weight	1875 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	100921224733244DT