





report date: 2024-03-28

General information

Make	MAZDA
Model	6 SPORT
Colour	White
Year of manufacture	2013
Top speed	133 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-01

Pictures 10

Listing price View report









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-13
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	5
Total items failed	5

MOT #10	2023-12-19 12:42
MOT test number	765272598948
Result	✓ Passed
Next expiry date	2025-01-13

MOT #9	2023-01-12 17:24
MOT test number	390220896771
Result	✓ Passed

MOT #8		2022-01-14 12:33
MOT test	number	852782349680
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Inner Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2021-01-14 17:40
MOT test number	810459536461
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

		2022 00 01 12 50
MOT #	6	2020-08-01 13:59
MOT te	est number	550982221635
Result		✓ Passed
MOT #	5	2019-05-06 14:17
MOT te	est number	388966125002
Result		✓ Passed
MOT #	4	2019-05-06 11:28
MOT te	est number	853868532213
Result		≍ Failed
Fail	Parking brake lever has excessive movement indicating incorrect adjustment (1.3	L.6 (c))
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))	
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
Fail	Nearside Rear Service brake excessively binding (1.2.1 (f))	

MOT #3	2018-04-11 13:23
MOT test number	415508768312
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #2	2017-03-16 12:20
MOT test number	976562474633
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2016-02-26 15:20

MOT test number 283505735820

Result ✓ Passed

Advice

Nearside front tyre starting to wear low 3mm

CarCheck.co.uk page 5/12





report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	13 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MAZDA salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NK.
Plate since	
Current registration	NK SILE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-03-28
Last registration	2023-12-19
Complete history	See info



2013-03-28	15 mi
2016-02-26	37.124 mi
2017-03-16	46.167 mi
2018-04-11	57.736 mi
2019-05-06	69.071 mi
2019-05-06	69.071 mi
	91.777 es
	11.777 es
	2016-02-26 2017-03-16 2018-04-11 2019-05-06

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1475 mm
Length	4800 mm
Wheel base	2750 mm
Kerb weight	1310 kg
Max. allowed weight	1990 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	PE 30483597

CarCheck.co.uk page 12/12