



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BORA S TDI (100BHP)
Colour	Black
Year of manufacture	2005
Top speed	117 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	325 Nm at 1.800 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-27
Pictures	23
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-19
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	29
Total items failed	6

MOT #21	2023-12-20 11:04
MOT test number	297894656921
Result	✓ Passed
Next expiry date	2024-12-19
Advice	Both front tyres wearing on edges

MOT #20	2023-12-12 11:05
MOT test number	128798100064
Result	✗ Failed
Fail	Offside Rear Service brake excessively binding (1.2.1 (f))
Advice	Both front tyres wearing on edges
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Rear Exhaust mounting bracket detached

**MOT #19**

2022-11-25 12:14

MOT test number

469340076821

Result

✓ Passed

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Front Exhaust has a minor leak of exhaust gases Section (6.1.2 (a))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #18**

2021-12-07 09:03

MOT test number

898070167134

Result

✓ Passed

Minor Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Centre exhaust leak**MOT #17**

2021-11-30 11:12

MOT test number

962027880000

Result

✗ Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))**Minor** Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Centre exhaust leak**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**MOT #16**

2020-11-28 08:46

MOT test number

764623294360

Result

✓ Passed

**MOT #15** 2019-12-09 15:19**MOT test number** 802960185096**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front brake discs corroded**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2019-12-09 09:15**MOT test number** 283283536763**Result** ✗ Failed**Advice** Front brake discs corroded**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2018-11-26 10:47**MOT test number** 646631777773**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge also nail in tyre (5.2.3 (e))**MOT #12** 2017-12-01 12:21**MOT test number** 904509956724**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2016-12-14 09:17**MOT test number** 529381130116**Result** ✓ Passed**Advice** Offside Front Tyre worn on inner edge**MOT #10** 2015-12-08 09:13**MOT test number** 829979088178**Result** ✓ Passed**MOT #9** 2014-11-26 14:16**MOT test number** 858190534373**Result** ✓ Passed**MOT #8** 2013-11-19 10:49**MOT test number** 305683223396**Result** ✓ Passed**MOT #7** 2013-11-18 10:24**MOT test number** 947222723387**Result** ✗ Failed**Fail** Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #6** 2012-11-19 15:39**MOT test number** 889114922376**Result** ✓ Passed**MOT #5** 2012-11-19 10:26**MOT test number** 945214522347**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)



MOT #4	2011-11-18 14:45
MOT test number	478632621423
Result	✓ Passed
MOT #3	2010-11-25 14:38
MOT test number	562809620312
Result	✓ Passed
MOT #2	2009-11-18 10:38
MOT test number	931212729378
Result	✓ Passed
MOT #1	2008-11-18 10:40
MOT test number	853503028349
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear brake disc slightly pitted (3.5.1h)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake disc slightly pitted (3.5.1h)



Tax & MOT check

X

Untaxed

Tax expired:
15 January 2024

✓

MOT

Expires:
19 December 2024

Tax status	Expired at 15 January 2024
Days left	106 days too late
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-12-16
Last registration	2023-12-20
Complete history	See info



Registration #1	2005-12-16	9 mi
Registration #2	2008-11-18	15.055 mi
Registration #3	2009-11-18	19.413 mi
Registration #4	2010-11-25	24.480 mi
Registration #5	2011-11-18	28.831 mi
Registration #6	2012-11-19	34.198 mi
Registration #7	2012-11-19	34.200 mi
Registration #8	2013-11-18	39.279 mi
Registration #9	2013-11-19	39.279 mi
Registration #10	2014-11-26	45.605 mi
Registration #11	2015-12-08	50.778 mi
Registration #12	2016-12-14	56.234 mi
Registration #13	2019-05-20	56.234 mi
Registration #14	2019-05-20	56.234 mi
Registration #15	2019-05-20	56.234 mi
Registration #16	2019-05-20	56.234 mi
Registration #17	2019-05-20	56.234 mi
Registration #18	2019-05-20	56.234 mi
Registration #19	2019-05-20	56.234 mi
Registration #20	2019-05-20	56.234 mi
Registration #21	2019-05-20	56.234 mi
Registration #22	2019-05-20	56.234 mi
Registration #23	2019-05-20	56.234 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

ASZ546881