





report date: 2024-03-29

## General information

Make	PEUGEOT
Model	308 BLUE HDI S/S GT
Colour	Blue
Year of manufacture	2015
Top speed	137 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	178 BHP
Max. torque	399 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	80.7 mpg
Consumption combined	70.6 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/12



## Internet history

### Entry 4

Date 2023-03-05

Pictures 12

Listing price <u>View report</u>









#### source: cargurus.co.uk

#### Entry 3

Date	2021-07-03
------	------------

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 2

Date	2021-06-22

Pictures 1

Listing price <u>View report</u>



source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-10
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #8	2024-02-09 16:58
MOT test i	number 716919910728
Result	✓ Passed
Next expi	ry date 2025-02-10
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Advice	Front UNDER TRAY INSECURE
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
<b>Advice</b> (5.2.3 (e))	Nearside Tyre worn close to legal limit/worn on edge 1.6MM /FLAT SPOTS NEEDS REPLACING ASAP
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b> (5.2.3 (e))	Offside Front Tyre worn close to legal limit/worn on edge 2.5MM CLOSE TO CORDS INNER EDGE
Advice	Offside Front WHEEL ARCH LINER INSECURE
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
<b>Advice</b> requires ac	Rear Brakes imbalanced requirements only just met. It would appear that the braking system djustment or repair. (1.2.1 (b) (i))
<b>Advice</b> (5.2.3 (e))	Nearside Front Tyre worn close to legal limit/worn on edge 3MM CLOSE TO CORDS INNER EDGE
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 3/12



Result

G17CDB report date: 2024-03-29

**X** Failed

MOT #7 2023-02-11 14:59
MOT test number 260266302609

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2023-02-11 14:59

**MOT test number** 266573421022

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Nearside Front Headlamp aim too high (4.1.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2022-03-19 13:58

**MOT test number** 798340094688

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2021-05-31 11:53

**MOT test number** 847490311245

**Result** ✓ Passed

MOT #3 2020-05-28 14:00

**MOT test number** 566388285766

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



MOT #2 2019-06-07 11:53

**MOT test number** 484164575770

**Result** ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #1** 2018-05-08 15:17

**MOT test number** 773927312973

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	10 February 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



<b>O</b>	history
IWADAL	
	IIISLUIV

e when moterly	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
********	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	OK SIE SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



## Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-05-16
Last registration	2024-02-09
Complete history	See info



Registration #1	2015-05-16	16 mi
Registration #2	2018-05-08	45.491 mi
Registration #3	2019-06-07	57.561 mi
Registration #4	2020-05-28	67.898 mi
Registration #5	2021-05-31	75.803 mi
Registration #6		71.777 46
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es
Registration #10		11.777 es
Registration #11		D.707 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



# Car features

S0225	Air conditionin
S0295	
50482	
50501	
60566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	79%
Pedestrian	64%
Safety systems	81%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1804 mm
Height	1457 mm
Length	4253 mm
Wheel base	2620 mm
Kerb weight	1320 kg
Max. allowed weight	1920 kg

# Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number DYZN4024241