





report date: 2024-03-29

General information

Make	MINI
Model	COUNTRYMAN COOPER SD ALL4 COOPER SD ALL4
Colour	Silver
Year of manufacture	2011
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	57.7 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2022-06-23

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-04-27
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	17
Total items failed	8

MOT #14	2024-04-24 11:16
MOT test number	901804948098
Result	X Failed
Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	
Minor Offside Front Position lamp insecure (4.2.1 (c) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))	
Fail Nearside Rear Upper Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)	<i>(</i>)
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))

MOT #13	2023-04-03 14:45
MOT test number	459322577765
Result	✓ Passed
MOT #12	2023-04-01 11:25
MOT test number	741723469465
Result	X Failed
Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure	e of its structure (5.2.3 (d) (ii))

CarCheck.co.uk page 3/13



Fail

CF11JFU report date: 2024-03-29

MOT #11 2022-04-27 10:28 **MOT** test number 879640686051 Result ✓ Passed MOT #10 2021-04-28 14:18 **MOT** test number 615707073062 ✓ Passed Result **MOT** #9 2021-04-28 11:00 **MOT** test number 682386418400 Result × Failed Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Windscreen washer not working (3.5 (a))

MOT #8 2019-11-28 09:19 **MOT** test number 518875441029 ✓ Passed Result **MOT #7** 2019-11-28 09:19 **MOT test number** 514423383894 Result × Failed Pass with rectification Offside Headlamp aim too high (4.1.2 (a)) **Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #6

MOT test number

421372706024

Result

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

CarCheck.co.uk page 4/13



Advice

CF11JFU report date: 2024-03-29

MOT #5

MOT test number

Result

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Handbrake travel high but has reserve

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT test number

Result

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front number plate cracked

MOT #3

MOT test number

686694714746

Result

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front number plate cracked

Advice Parking brake lever has little reserve travel (3.1.6b)

MOT #2

MOT test number

Result

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



MOT #1 2014-05-22 12:24

MOT test number 506612144137

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	27 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-


CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>k</u>		?

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	NK SIE	
Plate since		
Current registration	NK NIN	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-06-30
Last registration	2024-04-24
Complete history	See info



Registration #1	2011-06-30	9 mi
Registration #2	2014-05-22	17.346 mi
Registration #3	2015-10-01	23.340 mi
Registration #4	2016-11-22	26.732 mi
Registration #5	2017-11-22	29.220 mi
Registration #6	2018-11-14	32.487 mi
Registration #7	2018-11-15	32.487 mi
Registration #8	2019-11-28	34.757 mi
Registration #9		11.177 es
Registration #10		11.177 es
Registration #11		11.777 es
Registration #12		77,777 46
Registration #13		11.177 es
Registration #14		D.777 es
Registration #15		11.177 mi

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2670 mm
Kerb weight	1395 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	51 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 13/2

Number of axles 2

Engine number 72677821