



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE SPORT
Colour	Blue
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-12-07
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-04-27
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	20
Total items failed	5

MOT #16	2023-04-28 08:19
MOT test number	997778542396
Result	✓ Passed
Next expiry date	2024-04-27
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2023-04-18 09:04
MOT test number	531952027918
Result	✗ Failed
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-04-22 13:30
MOT test number	905227310757
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13** 2022-04-22 11:41**MOT test number** 626985148201**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2021-08-06 08:05**MOT test number** 609128141611**Result** ✓ Passed**MOT #11** 2020-07-30 09:57**MOT test number** 587346580888**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #10** 2019-08-13 12:27**MOT test number** 874111733515**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9** 2018-08-03 13:56**MOT test number** 373242625686**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2017-08-03 10:23**MOT test number** 384948337003**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #7** 2016-09-14 13:51**MOT test number** 823346056494**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 2.5mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1)**MOT #6** 2015-10-01 14:29**MOT test number** 573153135708**Result** ✓ Passed**MOT #5** 2015-09-30 09:51**MOT test number** 118233786023**Result** ✗ Failed**Advice** Offside Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear tyre worn on outside edge**Fail** Nearside Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #4	2014-03-25 11:39
MOT test number	988394784020
Result	✓ Passed
MOT #3	2013-03-28 09:24
MOT test number	906457583098
Result	✓ Passed
MOT #2	2012-03-27 11:11
MOT test number	335577282079
Result	✓ Passed
MOT #1	2011-03-30 08:54
MOT test number	509299781066
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✗
MOT

Expired:
27 April 2024

Tax status	Valid until 1 May
Days left	1
MOT expiry date	27 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-28
Last registration	2023-04-28
Complete history	See info



Registration #1	2008-03-28	24 mi
Registration #2	2011-03-30	47.843 mi
Registration #3	2012-03-27	50.965 mi
Registration #4	2013-03-28	54.651 mi
Registration #5	2014-03-25	58.382 mi
Registration #6	2015-09-30	60.787 mi
Registration #7	2015-10-01	60.795 mi
Registration #8	2016-09-14	68.621 mi
Registration #9	2017-08-03	74.979 mi
Registration #10	2018-05-29	81.337 mi
Registration #11	2019-05-29	88.695 mi
Registration #12	2020-05-29	96.053 mi
Registration #13	2021-05-29	103.411 mi
Registration #14	2022-05-29	110.769 mi
Registration #15	2023-04-28	118.127 mi
Registration #16	2023-04-28	118.127 mi
Registration #17	2023-04-28	118.127 mi
Registration #18	2023-04-28	118.127 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1778 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	560100