



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO ELEGANZA
Colour	Blue
Year of manufacture	2007
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-07
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-03
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	25
Total items failed	11

MOT #18	2023-05-19 07:40
MOT test number	357200469789
Result	✓ Passed
Next expiry date	2024-06-03

MOT #17	2022-05-27 08:07
MOT test number	487061726168
Result	✓ Passed
Advice	Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16	2021-06-04 15:12
MOT test number	576334277840
Result	✓ Passed

**MOT #15** 2021-06-02 08:01**MOT test number** 731306086385**Result** ✗ Failed

- Fail** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
- Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #14 2020-02-08 17:09**MOT test number** 937299300619**Result** ✓ Passed**MOT #13** 2019-01-08 16:27**MOT test number** 704218531078**Result** ✓ Passed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #12 2018-01-06 12:39**MOT test number** 460077933388**Result** ✓ Passed

- Advice** Parking brake lever ratchet mechanism is slightly worn (3.1.5)
- Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #11** 2018-01-06 12:39**MOT test number** 456987280584**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Parking brake lever ratchet mechanism is slightly worn (3.1.5)**MOT #10** 2017-01-31 09:22**MOT test number** 934391728374**Result** ✓ Passed**MOT #9** 2017-01-30 15:30**MOT test number** 207844036976**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #8** 2016-01-20 11:22**MOT test number** 895711752153**Result** ✓ Passed**Advice** Exhaust corroded

**MOT #7** 2015-01-21 11:04**MOT test number** 148651225097**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Wipers starting to smear**MOT #6** 2014-01-22 10:42**MOT test number** 186372424070**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Slight wear front brake discs**MOT #5** 2014-01-22 10:42**MOT test number** 895642524096**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Slight wear front brake discs**MOT #4** 2013-01-28 15:24**MOT test number** 886028923002**Result** ✓ Passed**Notice** Slight damage to sills**Notice** Stone chips in windscreen**Notice** Front discs worn**Notice** Exhaust corroded



MOT #3	2012-01-20 11:40
MOT test number	877140022069
Result	✓ Passed
Notice	Deep cut to o/s/r tyre
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Sign of coolant leaking from behind cambelt cover
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2011-01-28 11:48
MOT test number	605728221085
Result	✓ Passed

MOT #1	2010-01-28 11:14
MOT test number	571328020095
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
8 July 2023

✓

MOT

Expires:
3 June 2024

Tax status	Expired at 8 July 2023
Days left	297 days too late
MOT expiry date	3 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-01-22
Last registration	2023-05-19
Complete history	See info



Registration #1	2007-01-22	26 mi
Registration #2	2010-01-28	9.586 mi
Registration #3	2011-01-28	13.282 mi
Registration #4	2012-01-20	16.482 mi
Registration #5	2013-01-28	19.633 mi
Registration #6	2014-01-22	22.168 mi
Registration #7	2015-01-21	29.985 mi
Registration #8	2016-01-20	37.903 mi
Registration #9	2017-01-30	39.936 mi
Registration #10	2017-01-31	39.936 mi
Registration #11	2018-05-29	39.936 mi
Registration #12	2019-05-29	39.936 mi
Registration #13	2020-05-29	39.936 mi
Registration #14	2021-05-29	39.936 mi
Registration #15	2022-05-29	39.936 mi
Registration #16	2023-05-19	39.936 mi
Registration #17	2023-05-19	39.936 mi
Registration #18	2023-05-19	39.936 mi
Registration #19	2023-05-19	39.936 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3947109