



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 HDI SW ACTIVE
Colour	Black
Year of manufacture	2013
Top speed	113 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-03
Pictures	7
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2022-04-04
-----------------	------------

MOT pass rate	56 %
---------------	------

MOT passed	5
------------	---

Failed MOT tests	4
------------------	---

Total advice items	31
--------------------	----

Total items failed	5
--------------------	---

MOT #9	2021-04-05 13:29
--------	------------------

MOT test number	762378180949
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2022-04-04
------------------	------------

MOT #8	2021-04-02 12:48
--------	------------------

MOT test number	573390856943
-----------------	--------------

Result	✗ Failed
--------	----------

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MAJOR Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Nearside Rear Service brake excessively binding (1.2.1 (f))

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

Advice Rear Exhaust mounting defective (6.1.2 (a))

**MOT #7** 2019-11-27 16:59**MOT test number** 994403931141**Result** ✓ Passed**Advice** Offside Brake pipe corroded, covered in grease or other material Front on caliper (1.1.11 (c))**Advice** Nearside Brake pipe corroded, covered in grease or other material Front on caliper (1.1.11 (c))**MOT #6** 2019-11-27 11:03**MOT test number** 906506078016**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Brake pipe corroded, covered in grease or other material Front on caliper (1.1.11 (c))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Brake pipe corroded, covered in grease or other material Front on caliper (1.1.11 (c))**MOT #5** 2018-11-26 16:30**MOT test number** 378700026490**Result** ✓ Passed

**MOT #4** 2018-11-26 12:11**MOT test number** 706337856320**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear Position lamp not working (4.2.1 (a))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Exhaust hanger at rear broken**MOT #3** 2017-11-28 10:59**MOT test number** 706506439527**Result** ✓ Passed**Advice** Exhaust bracket at front pipe flex broken**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2016-11-02 16:40**MOT test number** 757316434051**Result** ✓ Passed



MOT #1

2016-11-02 09:37

MOT test number

611804486930

Result

✗ Failed

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail

Nearside Registration plate lamp not working (1.1.C.1d)

Advice

Both rear tyres wearing low

Fail

Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice

Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail

Offside Front position lamp(s) not working (1.1.A.3b)

Advice

Slight bind at nearside front wheel

Fail

Offside Registration plate lamp not working (1.1.C.1d)

Fail

Exhaust system not adequately supported At rear hanger (7.1.1)

Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✕
Untaxed

Tax expired:
1 October 2022

✕
MOT

Expired:
4 April 2022

Tax status	Expired at 1 October 2022
Days left	575 days too late
MOT expiry date	4 April 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	SY63NFZ
Plate since	2019-09-28
Current registration	SY63NFZ
Plate since	2019-09-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-11-29
Last registration	2021-04-05
Complete history	See info



Registration #1	2013-11-29	22 mi
Registration #2	2016-11-02	76.170 mi
Registration #3	2016-11-02	76.170 mi
Registration #4	2017-11-28	95.203 mi
Registration #5	2018-11-26	110.018 mi
Registration #6	2018-11-26	110.018 mi
Registration #7	2019-05-29	121.277 mi
Registration #8	2019-05-29	121.277 mi
Registration #9	2019-05-29	121.277 mi
Registration #10	2019-05-29	121.277 mi
Registration #11	2021-04-05	121.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	81%
Pedestrian	31%
Safety systems	97%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1972 mm
Height	1555 mm
Length	4149 mm
Kerb weight	1374 kg
Max. allowed weight	1743 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

JBFM3021536