



report date: 2024-03-28

General information

Make	FORD
Model	RANGER SUPER CAB 4X2 2.5D
Colour	White
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	195 Nm at 2.000 rpm
Engine capacity	2.500 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2025-01-24
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	50
Total items failed	10

MOT #19	2024-01-25 16:55
MOT test number	171410300872
Result	✓ Passed
Next expiry date	2025-01-24
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18	2021-12-17 18:59
MOT test number	697856171514
Result	✓ Passed
Advice	Lower Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Lower Vehicle structure is modified but structural rigidity is not significantly reduced (6.1.1 (d) (i))
Advice	Lower Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17**

2019-07-19 13:55

MOT test number

654498758071

Result

✓ Passed

- Advice** Rear Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i))
- Advice** Front and rear all suspension components corroded
- Advice** Front Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i))
- Advice** Both rear tyres wearing on the edges
- Advice** Under side of the vehicle corroded
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #16

2018-09-01 10:13

MOT test number

227280010730

Result

✓ Passed

- Advice** Suspension components+chassis members+brake pipes+ferrules corroding,exhaust brackets broken,rear tyres wearing on edges,
- Advice** Nearside Front slight brake binding

MOT #15

2017-09-14 07:33

MOT test number

377937919243

Result

✓ Passed

- Advice** Nearside front brake slight binding,rear tyres wearing on edges,exhaust mountings broken
- Advice** Brake load sensing valve stiff (3.6.E.3)
- Advice** Suspension components+chassis members+brake pipes+ferrules corroding
- Advice** Front crossmember corroded

**MOT #14** 2016-09-23 09:32**MOT test number** 423363776672**Result** ✓ Passed

- Advice** 2x exhaust brackets broken
- Advice** Areas of corrosion underneath
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Coolant on min

MOT #13 2016-09-23 08:50**MOT test number** 195113273253**Result** ✗ Failed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Coolant on min
- Advice** 2x exhaust brackets broken
- Fail** Nearside Front Headlamp aim too low (1.8)
- Advice** Areas of corrosion underneath

MOT #12 2015-08-24 15:44**MOT test number** 696390249772**Result** ✓ Passed

- Advice** Suspension components corroded, brake pipes + ferrules corroding
- Advice** Fuel tank damp
- Advice** Front crossmember corroded
- Advice** Towbar missing at time of test
- Advice** Offside front brake slight binding



MOT #11 2015-08-19 08:57

MOT test number 701204604095

Result ✗ Failed

Advice Suspension components corroded,brake pipes+ferrules corroding

Fail Nearside Stop lamp not working (1.2.1b)

Advice Fuel tank damp

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front crossmember corroded

Advice Towbar missing at time of test

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside front brake slight binding

MOT #10 2015-08-19 00:00

MOT test number 286912499194

Result ✗ Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Fuel tank damp

Advice Brake pipes+ferrules corroding

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside front brake slight binding

Advice Suspension components corroded,front crossmember corroded

Fail Nearside Stop lamp not working (1.2.1b)

**MOT #9** 2014-09-09 10:42**MOT test number** 859942754283**Result** ✓ Passed

Notice Offside front slight brake binding, brake pipes+ferrules+suspension components corroding, exhaust corroded+brackets broken still secure

MOT #8 2013-08-20 12:11**MOT test number** 125052033230**Result** ✓ Passed

Advice Brake pipe slightly corroded (3.6.B.2c)

Advice Brake pipe slightly corroded (3.6.B.2c)

Notice Heavy surface corrosion on suspension components.

Advice Brake pipe slightly corroded (3.6.B.2c)

Advice Vehicle structure has slight corrosion (6.1.B.2)

Notice Rear foot & hand brake imbalance.

MOT #7 2012-08-23 16:46**MOT test number** 756756132244**Result** ✓ Passed

Advice Brake pipe slightly corroded (3.6.B.2c)

Notice Surface corrosion on suspension components.

Advice Vehicle structure has slight corrosion (6.1.A.1)

MOT #6 2011-08-30 15:54**MOT test number** 309872441262**Result** ✓ Passed

**MOT #5** 2010-08-09 10:11**MOT test number** 253268310242**Result** ✓ Passed**MOT #4** 2009-08-12 11:02**MOT test number** 140924429254**Result** ✓ Passed**MOT #3** 2009-08-12 11:02**MOT test number** 400534329280**Result** ✗ Failed**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Rear registration plate dirty (6.3.1d)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #2** 2008-08-13 11:38**MOT test number** 580046028289**Result** ✓ Passed**MOT #1** 2008-08-13 11:38**MOT test number** 373046528468**Result** ✗ Failed**Pass with rectification** Nearside Rear Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)**Pass with rectification** Nearside Registration plate lamp not working (1.1.5c)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
24 January 2025

Tax status	Valid until 1 August
------------	----------------------

Days left	94
-----------	----

MOT expiry date	24 January 2025
-----------------	-----------------

Full MOT history	See MOT history
------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-08-24
Last registration	2024-01-25
Complete history	See info



Registration #1	2005-08-24	17 mi
Registration #2	2008-08-13	35.718 mi
Registration #3	2009-08-12	45.781 mi
Registration #4	2010-08-09	54.146 mi
Registration #5	2011-08-30	60.082 mi
Registration #6	2012-08-23	62.124 mi
Registration #7	2013-08-20	65.014 mi
Registration #8	2014-09-09	69.490 mi
Registration #9	2015-08-19	73.553 mi
Registration #10	2016-08-19	75.553 mi
Registration #11	2017-08-19	75.553 mi
Registration #12	2018-08-19	75.553 mi
Registration #13	2019-08-19	75.553 mi
Registration #14	2020-08-19	75.553 mi
Registration #15	2021-08-19	75.553 mi
Registration #16	2022-08-19	75.553 mi
Registration #17	2023-08-19	75.553 mi
Registration #18	2024-01-25	75.553 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	63 l
Fuel delivery	Indirect Injection
Number of doors	2
Number of seats	4
Engine number	524029