



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA HDI DESIRE PICASSO E4
Colour	Red
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-10-23
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-10-22
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-01
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	32
Total items failed	16

MOT #20	2023-11-01 11:26
MOT test number	589538842512
Result	✓ Passed
Next expiry date	2024-11-01
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #19	2022-10-24 08:45
MOT test number	980697390995
Result	✓ Passed
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #18	2021-11-02 17:49
MOT test number	735898923013
Result	✓ Passed

**MOT #17** 2021-11-01 15:09**MOT test number** 660277520489**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #16** 2020-10-31 11:43**MOT test number** 777352680131**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Outer sidewall perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #15** 2019-05-01 14:46**MOT test number** 436762678227**Result** ✓ Passed**Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Oil leak engine area.**Advice** Offside Rear has kiddie seat fitted, adult belt not checked.**Advice** Rear exhaust bracket corroded. Attention soon.**MOT #14** 2018-05-02 14:28**MOT test number** 692750562046**Result** ✓ Passed

**MOT #13** 2018-04-20 16:03**MOT test number** 613153289868**Result** ✗ Failed**Fail** Offside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #12** 2017-08-01 07:44**MOT test number** 156219321394**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #11** 2017-07-31 09:33**MOT test number** 475611762304**Result** ✗ Failed**Fail** Offside Front Headlamp aim too low (1.8)**Fail** Front Horn not working (1.6.2a)**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2016-08-17 06:18**MOT test number** 526061656663**Result** ✓ Passed**MOT #9** 2016-03-14 16:10**MOT test number** 656046515985**Result** ✓ Passed

**MOT #8** 2016-03-14 11:30**MOT test number** 390939661693**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #7** 2015-03-16 07:55**MOT test number** 819025875001**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2015-03-16 07:55**MOT test number** 396035075004**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Exhaust system not adequately supported (7.1.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #5** 2014-02-21 11:09**MOT test number** 895502754016**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #4** 2013-03-12 11:09**MOT test number** 227951773041**Result** ✓ Passed

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Notice Child seat fitted not allowing full inspection of adult belt

MOT #3 2013-03-12 11:09**MOT test number** 788251373006**Result** ✗ Failed

Pass with rectification Front Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Notice Child seat fitted not allowing full inspection of adult belt

MOT #2 2012-03-09 16:27**MOT test number** 368039662081**Result** ✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

Notice Alltyres slightly perrishing



MOT #1

2012-03-09 12:13

MOT test number

175169462047

Result

✗ Failed

- Fail

Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)
- Notice

Engine covers fitted obscuring some components in the engine bay
- Fail

Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Notice

Nail in nearside rear tyre
- Notice

Under-trays fitted obscuring some underside components
- Fail

Nearside Front Direction indicator not working (1.4.A.2c)
- Notice

Alltyres slightly perrishing
- Notice

Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
1 November 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-03-19
Last registration	2023-11-01
Complete history	See info



Registration #1	2009-03-19	17 mi
Registration #2	2012-03-09	24.734 mi
Registration #3	2012-03-09	24.734 mi
Registration #4	2013-03-12	33.233 mi
Registration #5	2014-02-21	41.235 mi
Registration #6	2015-03-16	50.344 mi
Registration #7	2016-03-14	58.088 mi
Registration #8	2016-03-14	58.088 mi
Registration #9	2016-08-17	62.034 mi
Registration #10	2017-07-31	70.479 mi
Registration #11	2017-08-01	70.480 mi
Registration #12	2019-05-29	70.577 mi
Registration #13	2019-05-29	70.577 mi
Registration #14	2019-05-29	70.577 mi
Registration #15	2019-05-29	70.577 mi
Registration #16	2019-05-29	70.577 mi
Registration #17	2019-05-29	70.577 mi
Registration #18	2019-05-29	70.577 mi
Registration #19	2019-05-29	70.577 mi
Registration #20	2019-05-29	70.577 mi
Registration #21	2019-05-29	70.577 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBAW3025790