



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Blue
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-05-21
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-23
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	36
Total items failed	0

MOT #102023-05-24 07:57

MOT test number261966027722

Result✓ Passed

Next expiry date2024-05-23

- Advice** N/s/r suspension coil spring slightly corroded around lower coil
- Advice** Brake hose has slight corrosion to ferrule n/s/r and o/s/r (1.1.12 (f) (i))
- Minor** Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Power assisted steering pipe by o/s steering corroded slightly
- Advice** N/s/r and o/s/r suspension trailing arm front bush perished slightly
- Advice** N/s/r and o/s/r suspension lower link arm bushes worn/ perished slightly
- Advice** Coil spring corroded n/s/f and o/s/f (5.3.1 (b) (i))
- Advice** O/s engine mounting perished slightly
- Advice** N/s/f and o/s/f suspension lower arm rear bush worn/ perished slightly
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust front flexible join deteriorated slightly
- Advice** N/s/r and o/s/r suspension lower arm bushes perished slightly

**MOT #9**

2023-05-23 09:05

MOT test number

384556096455

Result**✗ Failed****Advice** Brake hose has slight corrosion to ferrule n/s/r and o/s/r (1.1.12 (f) (i))**Advice** N/s/r and o/s/r suspension lower link arm bushes worn/ perished slightly**Advice** O/s engine mounting perished slightly**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** N/s/f and o/s/f suspension lower arm rear bush worn/ perished slightly**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Exhaust front flexible joint deteriorated slightly**Advice** Coil spring corroded n/s/f and o/s/f (5.3.1 (b) (i))**Advice** N/s/r and o/s/r suspension lower arm bushes perished slightly**Advice** N/s/r suspension coil spring slightly corroded around lower coil**Minor** Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Power assisted steering pipe by o/s steering corroded slightly**MAJOR** Nearside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** N/s/r and o/s/r suspension trailing arm front bush perished slightly

**MOT #8** 2022-05-04 10:32**MOT test number** 387301598671**Result** ✓ Passed

- Advice** Brake hose has slight corrosion to ferrule both rear (1.1.12 (f) (i))
- Advice** Coolant leak coolant bottle split
- Advice** All direction indicators slightly discoloured both rear (4.4.3 (a))
- Advice** Offside Rear Anti-roll bar ball joint has slight play link arm (5.3.4 (a) (i))
- Advice** Coil spring corroded both front (5.3.1 (b) (i))
- Advice** Tyre worn close to legal limit/worn on edge both rear tyres wearing on inner edges (5.2.3 (e))
- Advice** Offside Front Brake disc worn, but not excessively inner side of brake disc limited braking surface (1.1.14 (a) (i))

MOT #7 2021-04-23 10:07**MOT test number** 296577085469**Result** ✓ Passed**MOT #6** 2020-05-07 12:24**MOT test number** 459131772173**Result** ✓ Passed**MOT #5** 2019-04-23 09:19**MOT test number** 334342287464**Result** ✓ Passed**MOT #4** 2018-04-26 14:59**MOT test number** 776995498697**Result** ✓ Passed



MOT #3	2017-05-16 13:26
MOT test number	537414661674
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2	2016-05-18 14:27
MOT test number	761376208099
Result	✓ Passed

MOT #1	2015-09-01 09:05
MOT test number	192515397325
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
23 May 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	23 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	FE62FWM
Plate since	2019-09-29
Current registration	FE62FWM
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2012-09-14
Last registration	2023-05-24
Complete history	See info



Registration #1	2012-09-14	19 mi
Registration #2	2015-09-01	20.868 mi
Registration #3	2016-05-18	24.701 mi
Registration #4	2017-05-16	33.672 mi
Registration #5	2018-04-26	40.332 mi
Registration #6	2019-04-23	46.185 mi
Registration #7	2020-05-20	55.277 mi
Registration #8	2021-05-20	55.277 mi
Registration #9	2022-05-20	55.277 mi
Registration #10	2023-05-24	55.277 mi
Registration #11	2023-05-24	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1097033