




report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D3 ES
Colour	Black
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-01-30
Pictures	14
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-15
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	26
Total items failed	6

MOT #15	2024-02-16 11:12
MOT test number	614810242615
Result	✓ Passed
Next expiry date	2025-02-15
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #14	2023-02-16 14:40
MOT test number	116297502953
Result	✓ Passed

MOT #13	2022-02-09 17:29
MOT test number	522278914877
Result	✓ Passed

MOT #12	2022-02-09 10:28
MOT test number	326943107931
Result	✗ Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #11**

2021-04-06 14:47

MOT test number

232083184577

Result

✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2021-04-06 11:51

MOT test number

391509419010

Result

✗ Failed

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Windscreen washer not working (3.5 (a))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9**

2020-03-17 14:16

MOT test number

661882374508

Result

✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #8	2019-03-26 15:27
MOT test number	646795447507
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7	2019-03-25 10:07
MOT test number	208350158811
Result	✗ Failed
Fail	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #6	2018-03-12 17:07
MOT test number	223580646844
Result	✓ Passed
Advice	REAR BRAKE DISCS CORRODED
Advice	FRONT BRAKE DISCS CORRODED
Advice	WHITE LIGHT REAR INDICATORS

MOT #5	2018-03-12 09:57
MOT test number	271681834844
Result	✗ Failed
Fail	Offside Front Front position lamp(s) not working (1.1.A.3b)
Advice	REAR BRAKE DISCS CORRODED
Advice	FRONT BRAKE DISCS CORRODED
Advice	WHITE LIGHT REAR INDICATORS

**MOT #4** 2017-02-22 16:03**MOT test number** 180100023959**Result** ✓ Passed**Advice** Under trays fitted unable to fully inspect**Advice** N/s & o/s outer sills plastic covers**MOT #3** 2016-02-22 11:22**MOT test number** 512828293477**Result** ✓ Passed**Advice** Nsr tyre stepped on inner edge**Advice** Osr tyre bold on inner edge / nail in tread area**MOT #2** 2015-02-20 11:28**MOT test number** 299281755011**Result** ✓ Passed**MOT #1** 2014-03-13 09:44**MOT test number** 999332774021**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
15 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	15 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	BJ11DFX
Plate since	2019-03-29
Current registration	BJ11DFX
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-19
Last registration	2024-02-16
Complete history	See info



Registration #1	2011-03-19	9 mi
Registration #2	2014-03-13	30.845 mi
Registration #3	2015-02-20	37.728 mi
Registration #4	2016-02-22	46.495 mi
Registration #5	2017-02-22	54.560 mi
Registration #6	2018-03-12	66.321 mi
Registration #7	2018-03-12	66.321 mi
Registration #8	2019-03-25	72.833 mi
Registration #9	2019-03-26	72.833 mi
Registration #10	2020-03-26	72.833 mi
Registration #11	2021-03-26	72.833 mi
Registration #12	2022-03-26	72.833 mi
Registration #13	2023-03-26	72.833 mi
Registration #14	2024-03-26	72.833 mi
Registration #15	2025-03-26	72.833 mi
Registration #16	2026-03-26	72.833 mi
Registration #17	2027-03-26	72.833 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1504 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1012435