



HONDA



RE6IZGB


report date: 2024-03-29

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	Blue
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 2


Date	2023-06-17
Pictures	19
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-30
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-14
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	25
Total items failed	1

MOT #11	2023-06-15 10:38
MOT test number	437804459945
Result	✓ Passed
Next expiry date	2024-06-14
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10	2023-06-02 11:44
MOT test number	765694237656
Result	✗ Failed
MAJOR	Nearside Front Headlamp aim too low (4.1.2 (a))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Front Driver's door cannot be opened from outside the vehicle door handle damaged (6.2.3 (a))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Nearside Front Body panel damaged and likely to cause injury wing (6.2.1 (a) (i))
MAJOR	Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))

**MOT #9** 2023-03-25 10:17**MOT test number** 516642279480**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Front Headlamp insecure (4.1.1 (c))
- Advice** Nearside Front wing damaged and only allows door to open half way.
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Nearside Rear Rear reflector missing (4.8.2 (a) (ii))
- MAJOR** Offside Front Driver's door cannot be opened from outside the vehicle (6.2.3 (a))
- DANGEROUS** Nearside Front Tyre has ply or cords exposed holes in tread (5.2.3 (d) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))
- MAJOR** Offside Front Bumper insecure (6.1.4 (a) (i))
- MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Nearside Obligatory mirror insecure (3.3 (b) (ii))

MOT #8 2022-04-04 16:32**MOT test number** 663966151968**Result** ✓ Passed

**MOT #7** 2021-04-03 10:47**MOT test number** 496809597915**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-07-13 15:33**MOT test number** 788209198165**Result** ✓ Passed**MOT #5** 2018-07-13 15:33**MOT test number** 952442454236**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too far to the right (4.1.2 (a))**MOT #4** 2017-07-05 08:53**MOT test number** 296711818289**Result** ✓ Passed**Advice** Rear brake discs slightly corroded on braking surface.**MOT #3** 2016-07-09 08:45**MOT test number** 895737549430**Result** ✓ Passed**MOT #2** 2015-07-13 11:52**MOT test number** 975384995100**Result** ✓ Passed



MOT #1	2014-09-08 16:59
MOT test number	906681054270
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
14 June 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	C
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-11-15
Last registration	2023-06-15
Complete history	See info



Registration #1	2011-11-15	22 mi
Registration #2	2014-09-08	35.449 mi
Registration #3	2015-07-13	43.611 mi
Registration #4	2016-07-09	56.484 mi
Registration #5	2017-07-05	60.501 mi
Registration #6	2018-07-13	66.805 mi
Registration #7	2018-07-13	66.805 mi
Registration #8	2019-06-20	66.805 mi
Registration #9	2019-06-20	66.805 mi
Registration #10	2019-06-20	66.805 mi
Registration #11	2019-06-20	66.805 mi
Registration #12	2019-06-20	66.805 mi
Registration #13	2019-06-20	66.805 mi
Registration #14	2019-06-20	66.805 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1004814