



PEUGEOT

MK57DGX

report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 S COUPE CABRIOLET
Colour	Red
Year of manufacture	-
Top speed	128 mph
0 - 60 mph	11.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	23.2 mpg
Consumption extra urban	44.8 mpg
Consumption combined	33.6 mpg





MOT history

MOT #19	2022-02-01 10:21
MOT test number	501311626232
Result	✓ Passed
Next expiry date	2023-01-31
Advice	Offside Front Steering arm deformed but serviceable (2.1.3 (c) (i))
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #18	2022-01-31 11:05
MOT test number	210243525310
Result	✗ Failed
Fail	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Offside Front Steering arm deformed but serviceable (2.1.3 (c) (i))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #17**

2021-02-01 16:59

MOT test number

591999442477

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Front Exhaust mounting defective (6.1.2 (a))

MOT #16

2020-01-27 15:16

MOT test number

543375821648

Result

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Nail in tyre

MOT #15

2020-01-27 11:48

MOT test number

772114400778

Result

✗ Failed

- Advice** Offside Front Play in steering rack inner joint(s)
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Nail in tyre
- Fail** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #14** 2019-01-24 08:24**MOT test number** 334734830526**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Play in steering rack inner joint(s)**Advice** Front Direction indicator slightly discoloured BOTH @ LIMIT (4.4.3 (a))**MOT #13** 2018-01-23 15:06**MOT test number** 894499603479**Result** ✓ Passed**MOT #12** 2017-08-25 14:44**MOT test number** 948874135041**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 2.0mm (4.1.E.1)**Advice** Direction indicator slightly discoloured both front (1.4.A.2f)**MOT #11** 2016-09-08 07:49**MOT test number** 791878231631**Result** ✓ Passed**MOT #10** 2016-08-30 14:35**MOT test number** 597531728470**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #9** 2016-07-28 08:41**MOT test number** 285152566686**Result** ✗ Failed**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-06-26 14:23**MOT test number** 678767575158**Result** ✓ Passed**MOT #7** 2015-06-26 14:23**MOT test number** 859247475146**Result** ✗ Failed**Pass with rectification** Nearside Front Brake hose excessively chafed (3.6.B.4d)**Pass with rectification** Nearside Rear coil spring broken (2.4.C.1a)**MOT #6** 2014-07-18 16:25**MOT test number** 175999594150**Result** ✓ Passed**MOT #5** 2013-07-12 16:47**MOT test number** 246953793484**Result** ✓ Passed

**MOT #4** 2012-07-25 15:05**MOT test number** 859207602238**Result** ✓ Passed**MOT #3** 2012-07-20 11:13**MOT test number** 366712002409**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Nail in offside rear tyre**MOT #2** 2011-08-16 13:07**MOT test number** 757558021297**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Nail in offside rear tyre**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2010-08-26 12:10**MOT test number** 861408830226**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-04
Last registration	2022-02-01
Complete history	See info



Registration #1	2007-09-04	20 mi
Registration #2	2010-08-26	23.754 mi
Registration #3	2011-08-16	31.040 mi
Registration #4	2012-07-20	44.638 mi
Registration #5	2012-07-25	44.690 mi
Registration #6	2013-07-12	56.402 mi
Registration #7	2014-07-18	58.739 mi
Registration #8	2015-06-26	61.442 mi
Registration #9	2016-07-28	68.992 mi
Registration #10	2016-08-30	69.664 mi
Registration #11	2019-05-29	75.377 mi
Registration #12	2019-05-29	75.377 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2019-05-29	75.377 mi
Registration #15	2019-05-29	75.377 mi
Registration #16	2019-05-29	75.377 mi
Registration #17	2019-05-29	75.377 mi
Registration #18	2019-05-29	75.377 mi
Registration #19	2019-05-29	75.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1573 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	LH5D1587853